



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2008148
INV Date 07/12/2020
Reference CC4/FCI20008042/Era3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SMM 4765C
Insured Veh. SHC 1608E
Claim No. D20003011MFSH
Policy No. D-20094922MFSH
Accident Date 28/07/2020
Inspection Date 11/08/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20008042/Era3q2

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 07-12-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1608E	Veh. Inspected	SMM 4765C
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20003011MFSH	Excess (\$)	0.00
Assign From	RACHEL WU	Assign Date	04/08/2020

2. Vehicle Particulars & Condition

Make & Model	MAZDA 6	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JM6GL1072K0312288	Colour	RED
Odometer	14239	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	BRIDGESTONE	4 mm
L/H Front Tyre	225/55 R17	BRIDGESTONE	4 mm
R/H Rear Tyre	225/55 R17	BRIDGESTONE	4 mm
L/H Rear Tyre	225/55 R17	BRIDGESTONE	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/07/2020	Inspection Date	11/08/2020
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 4765C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	1,026.50	1,026.50
1	RETAINER LHS	NOT NECESSARY	14.70	-
2	GROMMET ,FRONT BUMPER	NECESSARY	5.80	5.80
4	RIVET ,FRONT BUMPER	NECESSARY	18.00	18.00
2	FASTENER ,FRONT BUMPER	NECESSARY	6.00	6.00
8	RIVET ,FRONT BUMPER	NECESSARY	32.00	32.00
1	PROTECTOR LHS ,CHROME	NOT NECESSARY	65.80	-
1	COVER LHS ,CHROME	NOT NECESSARY	20.50	-
2	RIVET ,LICENCE PLATE HOLE	NOT NECESSARY	15.20	-
1	CHROME LHS	NOT NECESSARY	251.40	-
6	RIVET ,CHROME	NOT NECESSARY	55.20	-
8	RIVET ,GRILLE TOP	NOT NECESSARY	32.00	-
4	RIVET ,GRILLE TOP	NOT NECESSARY	32.00	-
1	HEADLAMP LHS	CUT	4,758.60	4,758.60
1	RIVET ,HEADLAMP	NECESSARY	3.50	3.50
3	CLIP ,HEADLAMP	NECESSARY	12.00	12.00
1	PROTECTOR LH ,HEADLAMP	NOT NECESSARY	102.40	-
1	FENDER LHS	NOT NECESSARY	383.70	-
1	STAY LHS ,FRONT FENDER	NOT NECESSARY	48.30	-
15	FASTENER ,MUDGUARD	NOT NECESSARY	45.00	-
			6,928.60	5,862.40
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
<u>LABOUR</u>				
TO REPLACE FRONT BUMPER AND FRONT FENDER LH .REPAIR ALL AREAS AFFECTED BY THE ACCIDENT .			1,650.00	660.00
TO RESPRAY FRONT BUMPER AND FRONT FENDER LH .			1,575.00	630.00
TO TRANSFER FRONT PEDESTRIAN SENSORS .			330.00	200.00
TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			250.00	120.00

Report Ref No. CC4/FCI20008042/Era3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CARRY -OUT BODY CAVITY PRESERVATION .	NOT NECESSARY	250.00	-
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			4,405.00	1,790.00
GRAND TOTAL			11,433.60	7,672.40
RECOMMENDED COST OF REPAIRS				7,672.40

Report Ref No. CC4/FC120008042/Era3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMM 4765C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

