Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20008048/R1PA3Q2

**Date:** 18/03/2021

**REFERENCE** 

Price:

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant SGX3830T Insured Vehicle No: SHA3021V

Vehicle No: SGX3839T Insured Vehicle No: SHA3921Y

Date of Loss: 30/07/2020 Nature of Claim: TP Claim No: MCT20070399

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SGX3839T

Make & Model: TOYOTA VIOS, 1.5 E (M) Engine No: 1NZX600002

Reg. Date: 22/08/2007 (Man. Year: 2007) Chassis No: MR053HY9305019028

Colour: Gold Odometer: 232600 km

Engine Capacity: 1497 cc Market Value/New Car N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,187.20	1,228.64	-41.44	-3.49
Miscellaneous Items	96.00	86.00	10.00	10.42
Labour	100.00	100.00	0.00	0.00
Paintwork Labour	292.44	292.44	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,675.64	1,707.08	-31.44	-1.88
Approved Total (Overridden) (S\$)		1,350.00		
(S\$)	1,675.64	1,350.00	325.64	19.43
+ GST 7.00/7.00% (S\$)	117.29	94.50	22.79	19.43
Nett Amount (S\$)	1,792.93	1,444.50	348.43	19.43
+ Car Rental (2.0 x S\$100.00/day -	+ 7.00% GST) (S\$)	214.00		
+ Do	c/Search Fee (S\$)	7.49		
	Nett Liability (S\$)	1,665.99		

**INSPECTION** 

Date of Assignment: 04/08/2020 Present Location: Mova Automotive Pte Ltd (Bukit

Merah)

Date Inspected: 24/08/2020 Inspected At: Mova Automotive Pte Ltd (Bukit

Merah)

Blk 1008, #01-04/06/08/94, Bukit

Merah Lane 3 Singapore 159722 Adjuster Report Page 2 of 4

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Feb 2021)

Parts: 143 TOYOTA VIOS 1.5 E (M) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SGX3839T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LOWER GRILLE	Cracked	-	*191.20 F
2	1	NA	*BUMPER REINFORCEMENT	Bent	299.70 F	*299.70 F
3	1	NA	*FRONT BUMPER	Scratched	498.60 F	*498.60 F
4	1	NA	*FRONT MANUFACT BADGE	Necessary	86.30 F	*86.30 F
5	1	NA	*GRILLE	Cracked	298.30 F	*298.30 F
6	1	NA	*L/BUMPER BRACKET	Serviceable	69.70 F	*- F
7	1	NA	*R/BUMPER BRACKET	Serviceable	69.70 F	*- F
8	1	NA	*RADIATOR GRILLE TRIM	Scratched	161.70 F	*161.70 F
F=Fra	anchise	part.		Sub Total (S\$)	1,484.00	1,535.80
			- Add. Disc. on L,N Items 20.00/20.00% (S\$)		296.80	307.16
				Total Parts (S\$)	1,187.20	1,228.64

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cellan	eous Items			
1	1	Audatex Fee (NECESSARY)		40.00	40.00
2	1	FRT NO PLATE (BENT)		45.00	35.00
3	1	OD/TP Case (Insurer)		11.00	11.00
			Sub Total (S\$)	96.00	86.00

## Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
vork Labour			
Гotal Paint Labour	New	200.00	200.00
Total Paint Materials	New	92.44	92.44
ır Items			
Total Panel/Mechanical Labour	New	100.00	100.00
	Gross Labour Cost (S\$)	392.44	392.44
T	otal Paint Labour otal Paint Materials r Items	Total Paint Labour  Total Paint Materials  Total Paint Materials  Total Panel/Mechanical Labour  New  New	Total Paint Labour New 200.00 Total Paint Materials New 92.44  Telems Total Panel/Mechanical Labour New 100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >