## **MOVA Automotive Pte Ltd** Blk 1008, Bukit Merah Lane 3, #01-04/06/08. Singapore 159722

**Insurer Reference:** 

Repairer Reference: CK138678

Date calculated: 12/01/2021 5:16 PM

**Full Report** Registration: SGX3839T

Printed: 12/01/2021 5:18 PM

**Summary Information** 

Claim

Location: Singapore (SG) Work Provider:

India International

Insurance

Printed by: Claim Reference:

Estimated Repair Time: Actual Repair Days:

GOH CHAI HOCK Currency:

Date of Incident:

Hire Car Start: Hire Car End:

30/07/20

SGD

**Vehicle Details** 

Vehicle

TOYOTA Manufacturer: **VIOS** Model: Sub Model: Е

Model Sheet Number: 70 F3 02 Registration: SGX3839T

VIN number: Odometer:


**Vehicle Condition** 

**Vehicle Status** 

Pre-Accident Damage: Date of Inspection:

**Damage Areas** 

All **Underbody** 



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

Code	Description		WU	Price SGD
B040)	ADJUST HEADLAMPS		2.0	10.00
NO NÚMBER	RENEW LEFT FRONT BRACKET		1.0	5.00
NO NUMBER	RENEW RIGHT FRONT BRACKET		1.0	5.00
B010	R + R FRONT BUMPER		5.0	25.00
B020)	RENEW FRONT BUMPER (REMOVED)		4.0	20.00
NO NUMBER	R + R FRONT BUMPER DAMPER		1.0	5.00
B010)	R + R FRONT BUMPER REINFORCEMENT		2.0	10.00
B020)	RENEW FRONT BUMPER REINFORCEMENT		2.0	10.00
B040)	R + R LEFT HEADLAMP  (BUMPER REMOVED)  DOES NOT INCLUDE: ADJUST HEADLAMP			5.00
B040)	R + R RIGHT HEADLAMP  (BUMPER REMOVED)  DOES NOT INCLUDE: ADJUST HEADLAMP			5.00
0317	L/F BUMPER BRACKET CHECK			
0318	R/F BUMPER BRACKET CHECK			
	Labour Cost Panel / Mechanical Labour	Hrs 2.00	WU 20.0	100.00
	Total of Labour			100.00

## **Paint**

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description	WU Price SGD
	BUMPER REINFORCEMENT SURFACE PAINT	5.0
	FRONT BUMPER NEW PART PAINT K1R	11.0
	FRT TOWING EYE COVER SURFACE PAINT PLAST. 3.0	
	L/F WING SURFACE PAINT	5.0
	R/F WING SURFACE PAINT	5.0

## **Paint Material Per Part**

Code	Description	Price SGD
0340	BUMPER REINFORCEMENT SURFACE PAINT	7.39
0281	FRONT BUMPER NEW PART PAINT K1R	44.67
0293	FRT TOWING EYE COVER SURFACE PAINT PLAST.	0.26
0741	L/F WING SURFACE PAINT	6.51
0742	R/F WING SURFACE PAINT	6.51

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	50.00 SGD/h			
Time Paint			29.0	
Preparation Main Work Metal		0.80	8.0	40.00
Preparation Comp. Work Plastic		0.30	3.0	15.00
Total	10 WU/h	4.00	40.0	200.00

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	44.67
Surface-/Blend Paint	20.41
Surface Painting Plastic	0.26
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	92.44

# **Spare Parts**

				prices as at 2015-06-01/01
Code	Description	Part Number	Part Source	Price SGD
0340	BUMPER REINFORCEMENT	52021 0D090	Original	299.70
0281	FRONT BUMPER	52119 0D996	Original	498.60
0431	FRONT MANUFACT BADGE	75301 0D010	Original	86.30
0410	GRILLE	53111 0D901	Original	298.30
0343	LOWER FRONT GRILLE	53112 0D120	Original	191.20
0411	RADIATOR GRILLE TRIM	53121 0D020	Original	161.70
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal Subtotal Discount(+	-20.00%)		0.00 1,535.80 -307.16
	Total			1,228.64

#### **Extras**

LALIAS		
Code	Description	Price SGD
1000	FRT NO PLATE	35.00*
1001	Audatex Fee	40.00*
1002	Merimen Fee	11.00*
	Total Extras	86.00

## **Final Calculation**

SGD	SGD
1,535.80	
-307.16	
	1,228.64
100.00	
	100.00
	86.00
200.00	
92.44	
	292.44
	1,707.08
	119.50
	1,826.58
	1,535.80 -307.16 100.00

### Comments

\* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS ) - WU PARTIAL INCL IN OTHER POSITIONS

## **Assessment Note**

Author	Date	Text
chgoh	12/01/2021 5:18 PM	Total \$1707.08 Lump Sum Repair \$1350.00 03 days