

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20008049/R1ES3Q2

Date: 28/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900005219
Claimant
Vehicle No : SLB1020H **Insured Vehicle No :** SMH3086L
Date of Loss: 31/07/2020 Nature of Claim: TP Claim No: 7906220665SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB1020H**
Make & Model: VOLKSWAGEN GOLF, 1.2 TSI (A) Engine No: CYV053336
Reg. Date: 28/03/2016 (Man. Year: 2015) Chassis No: WVVZZZAUZGW053450
Colour: Blue Odometer: 78246 km
Engine Capacity: 1197 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,341.15	3,679.25	661.90	15.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,950.00	5,170.00	4,780.00	48.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,291.15	8,849.25	5,441.90	38.08
+ GST 7.00/7.00% (S\$)	1,000.38	619.45	380.93	38.08
Nett Amount (S\$)	15,291.53	9,468.70	5,822.83	38.08
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,890.70		

INSPECTION

Date of Assignment: 05/08/2020
Date Inspected: 05/08/2020 Inspected At: Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934
Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HECKLAPPE: REAR BOOTLID	Bent	2,004.17 FS	*1,972.20 FS
2	1		*ADDITIONAL BRAKE LIGHT W	Serviceable	158.79 FS	*- FS
3	1		*1K WINDOW ADHESIVE	Necessary	49.51 FS	*49.51 FS
4	1		*ADHESIVE REMOVER	Necessary	114.78 FS	*114.78 FS
5	1		*PRIMER	Necessary	25.74 FS	*25.74 FS
6	2		*APPLICATOR	Necessary	18.78 FS	*18.78 FS
7	1		*ACTIVATOR FOR PRECOATED W	Necessary	23.77 FS	*23.77 FS
8	1		*INSCRIPTION BRIGHT CHROME: GOLF	Necessary	77.15 FS	*77.15 FS
9	1		*INSCRIPTION BRIGHT CHROME: TSI	Necessary	69.85 FS	*69.85 FS
10	1		*INSCRIPTION PURE WHITE / PO: BLUEMOTION	Necessary	77.56 FS	*77.56 FS
11	1		*VW SIGN	Not Necessary	82.55 FS	*- FS
12	1		*COVER FOR BUMPER PRIMED: REAR BUMPER	Deformed	1,165.55 FS	*1,165.55 FS
13	1		*ATTACHMENT STRIP: RR CTR BRACKET	Serviceable	64.97 FS	*- FS
14	1		*REAR DIFFUSER SATIN BLACK	Serviceable	323.62 FS	*- FS
15	4		*POP-RIVET	Necessary	4.36 FS	*4.36 FS
16	1		*NUMBER PLATE	Bent	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **4,341.15** **3,679.25**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC AND PROGRAMMING.	New	480.00	480.00
2	CHECK SHORT CIRCUIT / HARNESS REPAIR.	New	280.00	0.00
3	LABOUR.	New	3,360.00	1,680.00
4	TRANSFER BOOTLID MECHANISM.	New	840.00	420.00
5	R&R REAR WINDSCREEN.	New	840.00	840.00
6	CHECK WATER LEAK.	New	150.00	150.00
7	SPRAY PAINTING.	New	4,000.00	1,600.00
			Gross Labour Cost (\$\$)	5,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >