

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20008055/ACF3E2

**Date:** 30/06/2021

### REFERENCE

Insured/Claimant: TAN KEE SIN Policy No: 2100469178  
Date of Loss: 30/07/2020 Nature of Claim: OD Claim No: 6626332573SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGQ313A**  
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN003173  
Reg. Date: 30/04/2016 (Man. Year: 2015) Chassis No: WAUZZZF4XGA024898  
Colour: Silver Odometer: 65598 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$78,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17  
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm  
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	30,775.00	19,182.32	11,592.68	37.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,372.00	6,122.00	6,250.00	50.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>43,147.00</b>	<b>25,304.32</b>	<b>17,842.68</b>	<b>41.35</b>
<b>- Excess (S\$)</b>	300.00	300.00	0.00	0.00
<b>(S\$)</b>	42,847.00	25,004.32	17,842.68	41.64
<b>+ GST 7.00/7.00% (S\$)</b>	2,999.29	1,750.30	1,248.99	41.64
<b>Nett Amount (S\$)</b>	<b>45,846.29</b>	<b>26,754.62</b>	<b>19,091.67</b>	<b>41.64</b>

### INSPECTION

Date of Assignment: 05/08/2020  
Date Inspected: 04/08/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 10.0 days

**Adjuster:** ADRIAN LING

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,111.00 FS	*1,688.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	282.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Damaged	70.00 FS	*27.84 FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Cracked	194.00 FS	*154.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Torn	208.00 FS	*166.00 FS
6	1		*FRONT BUMPER AIR GUIDE - LH	Distorted	62.00 FS	*49.52 FS
7	1		*RADIATOR GRILLE	Cracked	1,799.00 FS	*1,439.20 FS
8	1		*FRONT BUMPER CARRIER	Bent	795.00 FS	*635.60 FS
9	1		*FRONT BUMPER BRACKET - LH	Damaged	225.00 FS	*180.00 FS
10	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	36.00 FS	*- FS
11	1		*FRONT BUMPER COVER	Cracked	126.00 FS	*100.40 FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	123.00 FS	*98.40 FS
13	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
14	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
15	1		*LOCK CARRIER BRACKET	Cracked	136.00 FS	*108.40 FS
16	2		*LOCK CARRIER BRACKET SUPPORT - LH / RH	Damaged	56.00 FS	*44.48 FS
17	1		*HORN - LH HIGH TONE	Cracked	124.00 FS	*99.20 FS
18	1		*SPRING SHACKLE	Bent	29.00 FS	*22.56 FS
19	1		*FRONT FENDER - LH	Repair	758.00 FS	*- FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	200.00 FS	*- FS
21	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	49.00 FS	*- FS
22	1		*FRONT FENDER BRACKET - LH	Not Necessary	35.00 FS	*- FS
23	1		*DEFORMATION ELEMENT BRACKET - LH	Not Necessary	49.00 FS	*- FS
24	1		*FRONT FENDER BRACE	Not Necessary	117.00 FS	*- FS
25	1		*WHEEL HOUSING LINER - LH	Not Necessary	237.00 FS	*- FS
26	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
27	1		*WHEEL SPOILER	Cracked	73.00 FS	*57.76 FS
28	1		*WHEEL SPOILER TRIM - LH	Missing	35.00 FS	*27.36 FS
29	1		*STONE CHIP GUARD	Necessary	50.00 FS	*40.72 FS
30	1		*BONNET	Dented	2,763.00 FS	*2,210.40 FS
31	1		*BONNET ATTACHMENT PARTS	Not Necessary	121.00 FS	*- FS
32	2		*BONNET LID HINGE - LH / RH	Not Necessary	602.00 FS	*- FS
33	1		*BONNET IMPACT PROTECTION - CENTRE	Necessary	27.00 FS	*21.52 FS
34	1		*BONNET IMPACT PROTECTION - LH	Necessary	28.00 FS	*21.84 FS
35	1		*BONNET IMPACT PROTECTION - RH	Necessary	27.00 FS	*21.52 FS
36	1		*TOP FENDER LEDGE COVER - UPPER	Not Necessary	31.00 FS	*- FS
37	1		*TOP FENDER LEDGE COVER - LOWER	Not Necessary	23.00 FS	*- FS
38	4		*BONNET GAS FILLED STRUT	Not Necessary	470.00 FS	*- FS
39	1		*BONNET STRIKER - LH / RH	N/S Bent	100.00 FS	*39.44 FS
40	2		*BONNET LID LOCK	Not Necessary	423.00 FS	*- FS
41	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	57.00 FS	*- FS
42	1		*BONNET BOWDEN CABLE	Not Necessary	57.00 FS	*- FS
43	1		*BONNET RELEASE LEVER	Not Necessary	13.00 FS	*- FS
44	1		*LED HEADLIGHT - LH	Cracked	7,693.00 FS	*6,154.40 FS
45	1		*MAIN LIGHT ELECTRONICS POWER MODULE	Damaged	739.00 FS	*591.20 FS
46	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	742.00 FS	*- FS
47	1		*HEADLIGHT HOSE - LH	Not Necessary	36.00 FS	*- FS
48	1		*HEADLAMP REPAIR KIT - LH	Damaged	130.00 FS	*104.00 FS
49	1		*COMPENSATING PIECE	Damaged	40.00 FS	*31.52 FS
50	1		*COMPENSATING PIECE	Damaged	40.00 FS	*31.52 FS
51	1		*COMPENSATING PIECE	Damaged	40.00 FS	*31.68 FS
52	1		*LIFT CYLINDER	Cracked	208.00 FS	*166.00 FS
53	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	92.00 FS	*- FS
54	1		*LOCK CARRIER	Cracked	1,004.00 FS	*803.20 FS
55	1		*COOLANT REGULATOR SUPPORT	Damaged	38.00 FS	*30.00 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*AIRCON CONDENSER	Dented	615.00 FS	*492.00 FS
57	1		*REFRIGERANT LINE	Bent	165.00 FS	*131.60 FS
58	1		*REFRIGERANT LINE	Bent	336.00 FS	*268.40 FS
59	1		*RADIATOR	Bent	647.00 FS	*517.60 FS
60	2		*RADIATOR RUBBER BUSH - LOWER	Necessary	18.00 FS	*13.76 FS
61	2		*RADIATOR RUBBER BUSH - LOWER	Necessary	24.00 FS	*19.20 FS
62	1		*ADDITIONAL RADIATOR	Dented	505.00 FS	*404.00 FS
63	1		*READY MIX COOLANT	Necessary	91.00 FS	*72.32 FS
64	1		*RADIATOR FAN RING	Cracked	242.00 FS	*193.60 FS
65	1		*RADIATOR FAN	Not Necessary	1,896.00 FS	*- FS
66	1		*RADIATOR AIR GUIDE	Deformed	28.00 FS	*22.08 FS
67	1		*RADIATOR AIR GUIDE - LH	Cracked	12.00 FS	*9.36 FS
68	1		*RADIATOR AIR GUIDE - UPPER	Damaged	16.00 FS	*12.72 FS
69	1		*RADIATOR AIR GUIDE - LOWER	Damaged	22.00 FS	*17.04 FS
70	1		*AIR INTAKE AIR DUCT - RH	Deformed	22.00 FS	*17.04 FS
71	1		*AIR INTAKE AIR GUIDE	Not Necessary	53.00 FS	*- FS
72	1		*NOISE INSULATION	Cracked	566.00 FS	*452.40 FS
73	1		*RADIATOR COOLANT HOSE	Not Necessary	51.00 FS	*- FS
74	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
75	1		*SUNDRIES	Necessary	350.00 FS	*128.24 FS
76	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Missing	361.00 FS	*288.80 FS
77	1		*TEMPERATURE SENSOR BRACKET (Supplementary)	Damaged	18.00 FS	*14.40 FS
78	1		*REFRIGERANT PIPE (Supplementary)	Bent	517.00 FS	*413.20 FS
79	1		*HORN SOCKET LHS (Supplementary)	Damaged	20.00 FS	*15.76 FS
80	1		*RADIATOR AIR GUIDE RHS (Supplementary)	Deformed	28.00 FS	*22.08 FS
81	1		*WHEEL SPOILER RHS (Supplementary)	Torn	73.00 FS	*57.76 FS
82	1		*COOLANT HOSE QUICK RELEASE COUPLING LOWER (Supplementary)	Damaged	159.00 FS	*127.20 FS
83	1		*REFRIGERANT LINE (Supplementary)	Bent	245.00 FS	*196.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 30,775.00 19,182.32**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TOW VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	280.00
3	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
4	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
5	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	New	350.00	0.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,900.00	2,250.00
7	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, HINGES AND LHS FRONT DOOR	New	4,200.00	1,650.00
8	TO CARRY OUT WHEEL ALIGNMENT CHECK	New	240.00	0.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
10	TO REMOVE AND RENEW AIRCOND REFRIGERANT PIPE. (FROM AIRCOND COMPRESSOR AND AIRCON CONDENSER TO CUT OFF POINT) (Supplementary)	New	300.00	300.00
			<b>Gross Labour Cost (\$\$)</b>	<b>12,372.00</b>
				<b>6,122.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >