

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20008056/ATF3E2

Date: 18/03/2021

REFERENCE

Insured/Claimant:	KATHURIA SWEETY	Policy No:	1900013841		
Date of Loss:	25/07/2020	Nature of Claim:	OD	Claim No:	3604753739SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH8014L	Engine No:	CVK075900
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF51KA024273
Reg. Date:	08/02/2019 (Man. Year: 2018)	Odometer:	81727 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$155,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,548.00	4,916.48	9,631.52	66.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	24,212.00	5,232.00	18,980.00	78.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,760.00	10,148.48	28,611.52	73.82
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	37,160.00	8,548.48	28,611.52	77.00
+ GST 7.00/7.00% (S\$)	2,601.20	598.39	2,002.81	77.00
Nett Amount (S\$)	39,761.20	9,146.87	30,614.33	77.00

INSPECTION

Date of Assignment:	05/08/2020		
Date Inspected:	04/08/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	9.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,504.00 FS	*2,003.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	163.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	220.00 FS	*- FS
4	1		*REAR BUMPER CHROME TRIM	Cracked	1,005.00 FS	*804.00 FS
5	1		*REAR BUMPER REFLECTOR - LH	Cut	41.00 FS	*32.24 FS
6	1		*TAIL LIGHT - LH	Cracked	1,129.00 FS	*903.20 FS
7	1		*TAIL LIGHT TRIM - LH	Not Necessary	30.00 FS	*- FS
8	1		*TAIL LIGHT - LH	Not Necessary	1,008.00 FS	*- FS
9	1		*TAIL LIGHT TRIM - RH	Not Necessary	30.00 FS	*- FS
10	1		*REAR BUMPER CARRIER	Not Necessary	886.00 FS	*- FS
11	2		*REAR BUMPER CARRIER SEAL	Not Necessary	28.00 FS	*- FS
12	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	44.00 FS	*- FS
13	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	44.00 FS	*- FS
14	2		*REAR PARKING AID SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS
15	1		*BOOT LID CONTROL UNIT	Not Necessary	399.00 FS	*- FS
16	1		*AERIAL RETAINER - LH	Not Necessary	25.00 FS	*- FS
17	1		*TELEPHONE AERIAL	Not Necessary	169.00 FS	*- FS
18	1		*VENT TRIM	Not Necessary	66.00 FS	*- FS
19	1		*REAR FENDER - LH	Repair	2,472.00 FS	*- FS
20	1		*SIDE WINDOW - LH	Not Necessary	709.00 FS	*- FS
21	1		*REAR SILENCER - LH	Not Necessary	873.00 FS	*- FS
22	1		*REAR SILENCER DUAL CLIP	Not Necessary	48.00 FS	*- FS
23	1		*REAR SILENCER BRACKET	Not Necessary	41.00 FS	*- FS
24	1		*EXHAUST TAILPIPES TRIM (NPA)	Not Necessary	0.00 FS	*- FS
25	2		*PACKING ADHESIVE	Not Necessary	36.00 FS	*- FS
26	1		*AUDI EMBLEM	Not Necessary	138.00 FS	*- FS
27	1		*AS INSCRIPTION	Not Necessary	95.00 FS	*- FS
28	1		*SILL PANEL TRIM ATTACHMENT PARTS	Not Necessary	129.00 FS	*- FS
29	1		*SILL PANEL TRIM ADHESIVE TAPES	Not Necessary	210.00 FS	*- FS
30	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
31	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
32	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
33	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
34	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
35	1		*SUNDRIES	Necessary	300.00 FS	*13.84 FS
36	1		*TAIL LAMP PANEL LHS	Bent	162.00 FS	*129.20 FS
37	1		*SET REAR BUMPER WIRING	Cut	664.00 FS	*530.80 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 14,548.00 4,916.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO RENEW 1/4 GLASS TO FACILITATE FENDER RENEWAL.	New	300.00	0.00
3	TO DISLOGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND SUDIO EQUIPMENT	New	1,400.00	0.00
4	TO REMOVE AND REINSTALL REAR SEAT, BLACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
5	TO DISMANTLE REAR BUMPER, REAR LID AND LHS SILL PANEL TRIM. CUT OUT AND WELD LHS REAR FENDER. TO RENEW REAR BUMPER RE-ORGANISE CRASH MANAGEMENT COMPONENTS. RE-INSTALL ALL PARTS REMOVED	New	7,200.00	500.00
6	TO RESPRAY REAR BUMPER, REAR LID, LHS REAR FENDER, LHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRIAN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	6,800.00	1,100.00
7	TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN POSITION	New	480.00	0.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
9	TO INSTALL SOLAR FILM FOR 1/4 GLASS	New	400.00	0.00
10	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BETTER MANAGER,FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO COMPONENTS	New	480.00	480.00
11	TO CUT OUT AND WELD LHS TAIL LAMP PANEL. TO REPAIR LHS REAR FENDER	New	3,600.00	1,500.00
12	TO RESPRAY LHS TAIL LAMP PANEL REAR END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALANT WORKS	New	1,600.00	1,100.00
Gross Labour Cost (\$\$)			24,212.00	5,232.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >