

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20008071/R1TF3E2

Date: 10/09/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBB7361C

Insured Vehicle No : GZ6140U

Date of Loss: 28/07/2020

Nature of Claim:

TP

Claim No: CDMCG20001001

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB7361C**

Make & Model: FIAT DOBLO, 1.3 D JTD (M)

Engine No: 199A20003217779

Reg. Date: 18/12/2009 (Man. Year: 2009)

Chassis No: ZFA22300005694695

Colour: Multi-colour

Odometer: 301279 km

Engine Capacity: 1248 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,694.57	6,588.16	2,106.41	24.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	1,350.00	1,030.00	43.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,074.57	7,938.16	3,136.41	28.32
Approved Total (Overridden) (S\$)		6,300.00		
(S\$)	11,074.57	6,300.00	4,774.57	43.11
+ GST 7.00/7.00% (S\$)	775.22	441.00	334.22	43.11
Nett Amount (S\$)	11,849.79	6,741.00	5,108.79	43.11

INSPECTION

Date of Assignment: 05/08/2020

Date Inspected: 05/08/2020 Inspected At:

Comfortdelgro Engineering Pte Ltd -

Pandan (HQ)

45 PANDAN ROAD

Singapore 609286

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2020)
Parts:	M1-MPV	FIAT DOBLO 1.3 D JTD (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB7361C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHS REAR TAIL GATE	Bent	1,831.41 FL	*1,831.41 FL
2	1		*REAR TAIL GATE WEATHERSTRIP - PN - 1	Necessary	292.41 FL	*292.41 FL
3	1		*REAR TAIL GATE SIDE SEAL - PN - 2	Necessary	328.51 FL	*328.51 FL
4	1		*LHS REAR TAIL GATE LOCK UPPER	Serviceable	166.35 FL	*- FL
5	1		*LHS REAR TAIL GATE LOCK LOWER	Cracked	166.35 FL	*166.35 FL
6	1		*LHS REAR TAIL GATE TRIM COVER	Cracked	250.20 FL	*250.20 FL
7	1		*3RD BRAKE LAMP	Serviceable	102.60 FL	*- FL
8	1		*LHS LISENCE PLATE LAMP	Serviceable	49.88 FL	*- FL
9	1		*RHS LISENCE PLATE LAMP	Serviceable	49.88 FL	*- FL
10	1		*WIPER NOZZLE JET	Serviceable	33.40 FL	*- FL
11	1		*LHS TAIL LAMP	Cracked	280.02 FL	*280.02 FL
12	1		*LHS TAIL LAMP GARNISH	Cracked	352.20 FL	*352.20 FL
13	1		*RHS REAR TAIL GATE - PN - 1	Bent	1,718.36 FL	*1,718.36 FL
14	1		*RHS REAR TAIL GATE LOCK UPPER - PN - 8	Serviceable	167.96 FL	*- FL
15	1		*RHS REAR TAIL GATE LOCK LOWER - PN - 9	Serviceable	166.35 FL	*- FL
16	1		*RHS TAIL GATE OUTER HANDLE - PN - 12	Serviceable	313.31 FL	*- FL
17	1		*STICKER COMPANY DECAL - BACK, LHS & RHS REAR	Necessary	1,200.00 FS	*900.00 FS
18	1		*STICKER - 70KM/H	Necessary	10.00 FS	*10.00 FS
19	1		*STICKER - 5 PAX (BLACK)	Necessary	10.00 FS	*10.00 FS
20	1		*REAR NUMBER PLATE	Scratched	45.00 FS	*35.00 FS
21	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
22	1		*REAR WINDSCREEN INNER SEAL	Necessary	40.00 FS	*40.00 FS
23	1		*REAR BUMPER - PN - 7	Deformed	281.20 FL	*281.20 FL
24	1		*REAR BUMPER LHS GARNISH - PN - 6	Cracked	241.68 FL	*241.68 FL
25	1		*REAR BUMPER RHS GARNISH	Serviceable	241.68 FL	*- FL
26	1		*REAR BUMPER RHS REFLECTOR - PN - 10	Missing	37.62 FL	*37.62 FL
27	1		*REAR BUMPER LHS REFLECTOR	Cracked	37.62 FL	*37.62 FL
28	1		*LHS REAR BUMPER SENSOR	Serviceable	352.30 FL	*- FL
29	1		*RHS REAR BUMPER SENSOR	Serviceable	352.30 FL	*- FL
30	1		*REAR REINFORCEMENT	Bent	352.60 FL	*352.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,511.19	7,205.18
- List Item Discount on L Items 10.00/10.00% (\$)	816.62	617.02
Total Parts (\$)	8,694.57	6,588.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY, SPRAY PAINT : RHS & LHS TAILGATE AND AFFECTED AREA	New	800.00	400.00
2	TO CHECK WIRING	New	30.00	30.00
3	TO REMOVE, RE FIT RHS & LHS TAIL GATE GLASS TO FACILITATE FOR REPAIR	New	150.00	120.00
4	TO REMOVE, RE FIX LHS & RHS TAIL GATE TRIM COVER, LOCK, HANDLE TO FACILITATE FOR REPAIR	New	200.00	100.00
5	TO REMOVE & REPLACE, RE ALIGN : LHS & RHS TAIL GATE, REAR BUMPER, AND AFFECTED AREA	New	1,200.00	700.00
Gross Labour Cost (S\$)			2,380.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >