

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20008073/AGQF3Q2

Date: 25/02/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001348254

Claimant
Vehicle No : SLD8132L

Insured Vehicle No : SJD5657H

Date of Loss: 03/08/2020

Nature of Claim: TP

Claim No: 246287

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD8132L**

Make & Model: TOYOTA WISH, 2.0 (A)

Engine No: 3ZRA440425

Reg. Date: 04/02/2010 (Man. Year: 2009)

Chassis No: JTDGJ20W905001842

Colour: White

Odometer: 127364 km

Engine Capacity: 1987 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,208.00	3,527.25	5,680.75	61.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,010.00	2,090.00	920.00	30.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	12,218.00	5,617.25	6,600.75	54.02
Approved Total (Overridden) (\$)		4,500.00		
Nett Amount (\$)	12,218.00	4,500.00	7,718.00	63.17

INSPECTION

Date of Assignment: 04/08/2020

Date Inspected: 05/08/2020 Inspected At:

Best Solution Autocare Pte Ltd (HQ)

53 UBI AVE 1 #03-01 PAYA UBI

INDUSTRIAL PARK

Singapore 408934

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Feb 2021)
Parts:	M1-MPV	TOYOTA WISH 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD8132L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	795.00 F	*588.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Necessary	194.00 F	*194.00 FL
3	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
4	2		*REAR BUMPER BRACKET	Not Necessary	190.00 F	*- FL
5	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	200.00 F	*200.00 FL
6	2		*REAR BUMPER REFLECTOR	Not Necessary	194.00 F	*- FL
7	1		*REAR END PANEL	Dented	670.00 F	*585.00 FL
8	1		*REAR END PANEL TOP GARNISH	Cracked	368.00 F	*295.00 FL
9	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 F	*10.00 FL
10	1		*TAILGATE TOYOTA EMBLEM	Necessary	78.00 F	*78.00 FL
11	1		*TAILGATE	Dented	1,768.00 F	*1,272.00 FL
12	1		*TAILGATE INNER LOCK (TOP)	Damaged	491.00 F	*361.00 FL
13	1		*TAILGATE INNER LOCK (LOWER)	Not Necessary	135.00 F	*- FL
14	1		*TAILGATE WINDSTRIP	Cut	421.00 F	*344.00 FL
15	1		*TAILGATE CHROME HANDLE (OUTER)	Not Necessary	378.00 F	*- FL
16	2		*TAILGATE REFLECTOR LAMP	Not Necessary	770.00 F	*- FL
17	1		*TAIL LAMP	O/s Cracked	1,308.00 F	*408.00 FL
18	1		*SET TAILGATE INNER TRIM BOARD CLIP	Not Necessary	50.00 F	*- FL
19	1		*TAILGATE INNER TRIM BOARD	Not Necessary	493.00 F	*- FL
20	1		*TAILGATE GLASS MOULDING	Necessary	365.00 F	*178.00 FL
21	1		*REAR NUMBER PLATE	Not Necessary	60.00 F	*- FL
22	1		*TAILGATE GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
23	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,208.00	4,663.00
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,135.75
Total Parts (\$)	9,208.00	3,527.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE DAMAGED PARTS,PANEL BEAT,REPAIR	New	1,000.00	800.00
2	TO PUTTY AND SPRAY PAINTING ON AFFECTED AREA	New	1,200.00	800.00
3	ANTI RUST	New	100.00	80.00
4	WIRING CHECK	New	80.00	30.00
5	R&R TAILGATE GLASS	New	150.00	120.00
6	R&R REVERSE SENSOR	New	80.00	50.00
7	R AND R VIDEO RECORDER	New	100.00	50.00
8	R AND R UPHOLSTERY	New	150.00	80.00
9	R AND R TAILGATE FITTINGS	New	150.00	80.00
Gross Labour Cost (\$)			3,010.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >