

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20008074/KVF3E2
Date: 25/09/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/20-412836
Claimant Vehicle No :	SMJ6179Y	Insured Vehicle No :	FBF2066S
Date of Loss:	31/07/2020	Nature of Claim:	TP
		Claim No:	MSC/V/20-000645

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ6179Y	Engine No:	LEB5615633
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71079485
Reg. Date:	13/03/2019 (Man. Year: 2018)	Odometer:	140881 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Windforce 8 mm	Rear Left Side:	APLUS 8 mm
Front Right Side:	Windforce 8 mm	Rear Right Side:	APLUS 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,184.50	2,950.40	4,234.10	58.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	1,840.00	2,340.00	55.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,364.50	4,790.40	6,574.10	57.85
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	11,364.50	3,800.00	7,564.50	66.56
+ GST 7.00/7.00% (S\$)	795.52	266.00	529.52	66.56
Nett Amount (S\$)	12,160.02	4,066.00	8,094.02	66.56

INSPECTION

Date of Assignment:	04/08/2020	
Date Inspected:	05/08/2020 Inspected At:	BLK 160 SIN MING DRIVE, #08-13 SIN MING AUTOCITY Singapore 575722 Repairer: Aero Garage Pte Ltd
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2020)
Parts: M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMJ6179Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked / Buckled	900.60 F	*900.60 FL
2	1		*FRONT BUMPER RETAINERS	O/S Distorted	39.00 F	*19.50 FL
3	2		*FRONT BUMPER BRACKETS	Repair	70.20 F	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	409.50 F	*- FL
5	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
6	1		*SIDE MIRROR ASSY RH	Cracked	1,004.30 F	*854.00 FL
7	1		*FRONT FENDER RH	Bent	546.20 F	*546.20 FL
8	1		*FRONT FENDER INNER SHIELD RH	Serviceable	95.60 F	*- FL
9	1		*FRONT SHOCK ABSORBER RH	Bent	351.10 F	*325.00 FL
10	1		*FRONT LOWER ARM RH	Distorted	243.80 F	*243.80 FL
11	1		*FRONT KNUCKLE ARM RH	Bent	360.80 F	*360.80 FL
12	1		*FRONT KNUCKLE ARM BEARING RH	Necessary	136.50 F	*136.50 FL
13	1		*FRONT WHEEL RIM RH	Dented	261.60 F	*261.60 FL
14	1		*SLIDING DOOR RH	Repair	1,179.80 F	*- FL
15	1		*REAR FENDER RH	Repair	1,345.50 F	*- FL
16	1		*FRONT TYRE RH	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,184.50	3,688.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	737.60
Total Parts (\$\$)	7,184.50	2,950.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS	New	1,800.00	600.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	1,500.00	1,000.00
3	TO REMOVE, REPLACE FENDERS AND DOOR FITTINGS TO FACILITATE REPAIR	New	400.00	0.00
4	TO REMOVE, REPLACE FRONT SHOCK ABSORBER, LOWER ARM AND KNUCKLE ARM	New	300.00	200.00
5	TO REMOVE, REPLACE FRONT TYRE AND WHEEL RIM	New	100.00	20.00
6	TO CHECK WIRING AND LIGHTINGS	New	80.00	20.00
Gross Labour Cost (S\$)			4,180.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >