

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20008076/KQF3E2

Date: 03/09/2020

REFERENCE

Insured/Claimant:	DAWOOD TRADING & WHOLESALE PTE LTD	Policy No:	DMCVSN30703619011
Date of Loss:	29/07/2020	Nature of Claim:	OD
		Claim No:	SNM20D202691C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ786P	Engine No:	YD25430376A
Make & Model:	NISSAN NV350, 2.5 (A)	Chassis No:	JN1MC2E26Z0009477
Reg. Date:	07/11/2018 (Man. Year: 2017)	Odometer:	74433 km
Colour:	Multi-colour		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Dunlop 2 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,943.96	7,073.77	11,870.19	62.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,500.00	1,640.00	6,860.00	80.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,443.96	8,713.77	18,730.19	68.25
Approved Total (Overridden) (S\$)		6,950.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	26,943.96	6,450.00	20,493.96	76.06
+ GST 7.00/7.00% (S\$)	1,886.08	451.50	1,434.58	76.06
Nett Amount (S\$)	28,830.04	6,901.50	21,928.54	76.06

INSPECTION

Date of Assignment: 05/08/2020
Date Inspected: 05/08/2020 Inspected At:

C.S. Ong Auto Pte Ltd (AMK)
BLOCK 10 ANG MO KIO IND PK 2A #04-01/#03-11
AMK AUTOPOINT
SINGAPORE 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Sep 2020)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ786P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Bent	1,650.30 FL	*1,206.00 FL
2	2		*FRONT QUARTER PANEL	Repair	1,069.20 FL	* - FL
3	2		*FRONT HEADLAMP	Mtg Cracked	1,282.80 FL	*1,282.80 FL
4	2		*FRONT HEADLAMP LOWER BRACKET	Repair	745.00 FL	* - FL
5	1		*FRONT GRILLE	Mtg Cracked	1,163.30 FL	*689.00 FL
6	1		*FRONT GRILLE NISSAN LOGO	Necessary	89.90 FL	*89.90 FL
7	1		*SET FRONT GRILLE CLIPS	Necessary	55.00 FL	*55.00 FL
8	2		*FOG LAMP COVER	Serviceable	320.20 FL	* - FL
9	3		*BRAKE PIPE	Serviceable	194.40 FL	* - FL
10	1		*FRONT SUPPORT PANEL ASSEMBLY	Repair	468.60 FL	* - FL
11	1		*FRONT BRACE PANEL	Repair	461.00 FL	* - FL
12	1		*FRONT BUMPER WITH CENTRE GRILLE	Buckled	531.90 FL	*531.90 FL
13	1		*SET FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
14	2		*FRONT BUMPER SIDE RETAINER LH & RH	Serviceable	450.00 FL	* - FL
15	1		*FRONT BUMPER REINFORCEMENT	Bent	805.00 FL	*390.70 FL
16	1		*FRONT RADIATOR	Serviceable	736.10 FL	* - FL
17	1		*WIPER WASHER MOTOR	Serviceable	243.60 FS	* - FS
18	1		*FRONT CENTRE GRILLE RADAR SENSOR ASSY	Serviceable	296.80 FS	* - FS
19	2		*FOG LAMP	Serviceable	847.40 FS	* - FS
20	1		*BRAKE VALVE	Serviceable	355.20 FS	* - FS
21	1		*AIR-CON HIGH PRESSURE PIPE	Serviceable	249.20 FS	* - FS
22	1		*AIR-CON LOW PRESSURE PIPE	Serviceable	269.20 FS	* - FS
23	1		*AIR-CON DISCHARGE PIPE	Serviceable	219.50 FS	* - FS
24	1		*AIR-CON COOLING COIL BOX (COMPLETE)	Cracked	2,290.60 FS	*1,685.00 FS
25	1		*AIR-CON BLOWER BOX	Serviceable	714.40 FS	* - FS
26	1		*FRONT INTERCOOLER	Serviceable	175.60 FS	* - FS
27	1		*FRONT BUMPER AIR HOSE	Serviceable	264.00 FS	* - FS
28	1		*FRONT RADIATOR TANK	Serviceable	150.30 FS	* - FS
29	1		*SET FRONT AIR-CON CONDENSER WITH FAN MOTOR	Serviceable	1,331.90 FS	* - FS
30	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	* - FS
31	1		*FRONT SUPPORT PANEL SEALANTS	Not Necessary	80.00 FS	* - FS
32	1		*FRONT NUMBER PLATE	Dented	80.00 FS	*20.00 FS
33	1		*OIL COOLANT UNIT	Punctured	2,243.40 FL	*1,500.00 FL
34	1		*FRONT BUMPER REINFORCEMENT BAR	Bent	250.30 FL	*185.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 20,199.10 7,670.30
- List Item Discount on L Items 10.00/10.00% (\$\$) 1,255.14 596.53

Total Parts (\$\$) 18,943.96 7,073.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DESIGN & PASTE FRONT COMPANY STICKER	New	1,800.00	0.00
2	TO CHARGE & DISCHARGE AIR-CON GAS }	New	100.00	100.00
3	TO REMOVE & REFIT FRONT AIR-CON CONDENSER & RADIATOR & TO CONDUCT PRESSURE TEST }	New	400.00	0.00
4	TO REMOVE DAMAGED FRONT INTERCOOLER & CONDUCT TURBO PRESSURE TEST	New	400.00	0.00
5	TO REPLACE DAMAGED FRONT RADAR SENSOR, DIAGNOSE & RESET TO FACTORY DEFAULT SETTINGS	New	500.00	0.00
6	TO REMOVE AND PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,500.00	600.00
7	TO RESPRAY NEW PAINTWORK ON ALL DAMAGED PARTS	New	1,500.00	500.00
8	TO REMOVE AND REFIT FRONT WINDSCREEN TO FACILITATE REPAIR	New	300.00	120.00
9	TO COMPUTERIZED REFOCUS FRONT HEADLAMP BEAM	New	120.00	20.00
10	TO ANTI-RUST COATINGS ON ALL AFFECTED AREAS	New	280.00	0.00
11	TO CHECK AND RE-FIX ALL ELECTRICAL WIRINGS	New	280.00	0.00
12	LABOUR CHARGE TO REMOVE AND REFIT DASHBOARD TO FACILITATE REPAIR	New	1,200.00	250.00
13	LABOUR CHARGE TO REMOVE AND REPLACE HEATER UNIT	New	120.00	50.00
Gross Labour Cost (\$\$)			8,500.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >