

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20008087/R1GS3Q2

Date: 22/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLU1314K	Insured Vehicle No :	SHD6523C
Date of Loss: 03/08/2020	Nature of Claim: TP	Claim No: MCT20080024

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU1314K		
Make & Model:	VOLKSWAGEN PASSAT VARIANT, 2.0 (A)	Engine No:	CHH298767
Reg. Date:	14/07/2020 (Man. Year: 2018)	Chassis No:	WVWZZZ3CZKE011790
Colour:	White	Odometer:	1017 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R19	Rear Tyre Size:	235/40 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,053.38	2,000.09	1,053.29	34.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	2,120.00	5,200.00	71.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,373.38	4,120.09	6,253.29	60.28
+ GST 7.00/7.00% (S\$)	726.14	288.41	437.73	60.28
Nett Amount (S\$)	11,099.52	4,408.50	6,691.02	60.28
+ Car Rental (3.0 x S\$120.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,775.95		

INSPECTION

Date of Assignment: 05/08/2020

Date Inspected: 06/08/2020 Inspected At: Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Sep 2020)
Parts:	143	VOLKSWAGEN PASSAT VARIANT 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU1314K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER PRIMED REAR BUMPER	Deformed	1,544.88 FS	*1,544.88 FS
2	1		*SPOILER PRIMED	Serviceable	286.50 FS	*- FS
3	1		*SET SENSOR BRACKETS	Necessary	43.74 FS	*43.74 FS
4	1		*BUMPER REINFORCEMENT	Repair	541.33 FS	*- FS
5	1		*ATTACHMENT STRIP RR CTR BRACKET	Not Necessary	58.90 FS	*- FS
6	5		*POP-RIVET	Necessary	5.45 FS	*5.45 FS
7	1		*DECORATIVE MOULDING BRIGH LHR	Scratched	166.56 FS	*166.56 FS
8	1		*DECORATIVE MOULDING BRIGH RHR	Serviceable	166.56 FS	*- FS
9	1		*DECORATIVE MOULDING BRIGH CTR	Damaged	216.66 FS	*216.66 FS
10	20		*POP -RIVET	Necessary	22.80 FS	*22.80 FS
Total Parts (S\$)					3,053.38	2,000.09

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
3	LABOUR	New	3,360.00	840.00
4	SPRAY PAINTING	New	3,200.00	800.00
Gross Labour Cost (\$\$)			7,320.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >