

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20008098/KPS3Q2
Date: 11/05/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100352459-06
Claimant Vehicle No :	SJG8660L	Insured Vehicle No :	SGB46A
Date of Loss:	17/07/2020	Nature of Claim:	TP
		Claim No:	6827146979SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG8660L		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B4431776
Reg. Date:	01/02/2018 (Man. Year: 2018)	Chassis No:	RU11231772
Colour:	Metallic Pearl White	Odometer:	38078 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	614.88	414.88	200.00	32.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	200.00	120.00	80.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	814.88	534.88	280.00	34.36
+ GST 7.00/7.00% (S\$)	57.04	37.44	19.60	34.36

Nett Amount (S\$)	871.92	572.32	299.60	34.36
+ Loss of Use (1.0 x S\$60.00/day) (S\$)		60.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		639.77		

INSPECTION

Date of Assignment: 05/08/2020

Date Inspected: 16/09/2020

Estimated Period of Repair: 1.0 days

Inspected At:

Lim Tan Motor Pte Ltd (HQ)
 Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care
 Singapore 575721

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Cut	518.60 FL	*518.60 FL
2	1		*REAR BUMPER SENSOR	Serviceable	200.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					718.60	518.60
- List Item Discount on L Items 20.00/20.00% (\$)					103.72	103.72
Total Parts (\$)					614.88	414.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES	New	200.00	120.00
Gross Labour Cost (\$)			200.00	120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >