

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
CYCLE & CARRIAGE LEASING PTE LTD  239 ALEXANDRA ROAD  SINGAPORE 159930  <b>Contact No Mobile: 85188668</b>	<b>Cust No/Name</b>	KC000162/ CYCLE & CARRIAGE LEASING PTE L
	<b>Reg No/Reg Date</b>	SMP6137L / 02/10/201
	<b>Date In/Mileage</b>	/ 0
	<b>Chassis No</b>	MMBSTA13AKH001917
	<b>Engine No</b>	3A92UHT2294
	<b>Make/Model</b>	MIT/19MY ATTRAGE 1.2 CVT
	<b>Colour/Trim</b>	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	04/08/2020/ 17:51	TLC	442 / CocoLu	55673

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, FRT FENDER LH, WINDMIRROR LH, REPAIR FRT DOOR LH, REAR DOOR LH				2200.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, FRT DOOR LH REAR DOOR LH, WINDMIRROR LH				2520.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00
M SUNDRY TRANSFER NEW RIM				30.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M SUNDRY Sundry				20.00
M FACE,FR BUMPER	1.00	703.00	00.00	703.00
M BRACKET,FR BUMPER,LH	1.00	13.00	00.00	13.00
M FENDER,FR LH	1.00	497.00	00.00	497.00
M GARNISH,FR PILLAR,LH	1.00	30.00	00.00	30.00
M MIRROR ASSY,DOOR,LH	1.00	638.00	00.00	638.00
M COVER,DOOR MIRROR,OTR LH	1.00	114.00	00.00	114.00
M WHEEL,DISC	1.00	687.00	00.00	687.00
M HUB ASSY,FR WHEEL	1.00	215.00	00.00	215.00
M BEARING,FR WHEEL HUB	1.00	121.00	00.00	121.00

Confirm & accepted by

<b>Nett</b>	<b>8,138.00</b>
<b>7% GST on</b>	<b>569.66</b>
<b>Total Payable</b>	<b>8,707.66</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.