

ASS. REC. BY:

REF:

C72/20008104/kk

C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop r/vs _____ Alan's

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PC1739R Yr Regn: 10, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Hina c.c. 2882Colour: White IR A/C: Insured / Std / NI / NASp. Reading: 139556 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTIFST22P300013953Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rlm / STD A/Rlm orTyre Size: F: 195R15X8

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 8 mmR/Bal. 8 mmL/Bal. 8 mmD.O.A. 7/7/20 D.O.I. 4/8/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Sumat report. (Reject Case)

Date/Time, File Pass to?

☐ : Prell. Report1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Fees _____

Others _____

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06201

Vehicle Insured : SGX4780X
Accident Date : 07-Jul-2020

Date : 29-Jul-2020

Our Ref : 020081 (CHINA) / CHAN

PAGE : 1

SINGAPORE RED CROSS SOCIETY
15 PENANG LANE
SINGAPORE RED CROSS
Singapore 238486

*Not Authorized
11 Pym &?
Money After Paint*

ESTIMATED COST OF REPAIR FOR TOYOTA HIACE 3.0 HIGH-ROOF PC1739R

5 days

1 pc	O/s taillamp	GR	256.90	✓
1 pc	O/s taillamp lower garnish	R	84.60	X
1 pc	Lower garnish bracket	R	36.40	X
1 pc	Rear bumper fascia	GR	373.70	✓
1 pc	Rear o/s bumper side retainer	R	31.80	X
1 pc	Rear o/s bumper side bracket	R	26.30	X
1 pc	Rear o/s fender	R	3,211.80	✓

4,021.50

Less 25% : 1,005.38

- 1 pc Rear o/s fender lettering
- 1 pc O/s fender glass sealant

3,016.12
R 300.00 sn ✓
R 180.00 sn *800*

To remove roof lining, front and rear seats, trim board and carpet

180.00 *120*

To putty and spray replaced parts

800.00 *600*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

1,000.00 *700*

To remove & refix o/s fender glass

200.00 *120*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total : S\$ 5,676.12

Singapore Dollars Five Thousand Six Hundred and Seventy Six and Cents Twelve Only