



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 7171J

| Qty                                | Description of Parts  | Condition   | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|-------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |   |             |                           |                   |
| 1                                  | FRONT SHOCK ABSORBER (N)  | INTACT      | 510.00                    | -                 |
| 1                                  | FRONT KNUCKLE ARM (N)   | INTACT      | 730.00                    | -                 |
| 1                                  | FRONT LOWER ARM (N)   | INTACT      | 530.00                    | -                 |
|                                    |   |             | 1,770.00                  | -                 |
| <b><u>SPECIAL NETT ITEMS</u></b>   |   |             |                           |                   |
| 1                                  | FRONT HEADLAMP (SN)   | DAMAGED     | 4,535.00                  | 3,800.00          |
| 1                                  | FRONT BUMPER (SN)   | DAMAGED     | 1,700.00                  | 1,500.00          |
| 1                                  | FRONT BUMPER SENSOR (SN)  | DAMAGED     | 275.00                    | 275.00            |
| 2                                  | STEERING TIRE ROD ENDS (SN)   | DAMAGED     | 402.00                    | 350.00            |
| 2                                  | STEERING BALL HEADS (SN)  | DAMAGED     | 392.00                    | 350.00            |
| 1                                  | FRONT BUMPER STICKER (SN)   | DAMAGED     | 380.00                    | 200.00            |
| 1                                  | FRONT TYRE (SN)   | SERVICEABLE | 400.00                    | -                 |
| 1                                  | SET FRONT SPORT RIM (SN)  | DAMAGED     | 1,800.00                  | 750.00            |
|                                    |   |             | 9,884.00                  | 7,225.00          |
| <b><u>LABOUR</u></b>               |   |             |                           |                   |
|                                    | TO PROVIDE TOWING SERVICE CHARGE.   |             | 60.00                     | 60.00             |
|                                    | TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.   |             | 80.00                     | 30.00             |
|                                    | TO REMOVE AND REFIT FRONT UNDERCARRIAGE.  |             | 400.00                    | 200.00            |
|                                    | TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT.  |             | 120.00                    | 60.00             |
|                                    | TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.                  |             | 500.00                    | 200.00            |
|                                    | TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE. |             | 500.00                    | 200.00            |
|                                    |   |             | 1,660.00                  | 750.00            |
| <b>GRAND TOTAL</b>                 |   |             | <b>13,314.00</b>          | <b>7,975.00</b>   |

Report Ref No. CS3/AIG19021393/Atf3e2-1



|   |  |  |                 |
|---|--|--|-----------------|
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)</b> |  |  | <b>6,400.00</b> |
|---|--|--|-----------------|

Report Ref No. CS3/AIG19021393/Atf3e2-1

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.