

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference: TP / 12-19008/DY / 2019

Date of Report : 10 Mar 2020

Lim Liang Wee Blk 132 Bedok Reservoir Road #05-1261 Eunos Spring Singapore 470132

THIRD PARTY SURVEY **ACCIDENT HAPPENED ON**

26 Nov 2019

As per your instruction dated 5 Dec 2019 with regard to the above matter. We have carried out a physical inspection on the said vehicle SJV 7171 J . We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SJV 7171 J

Model : Mercedes Benz C200

Year / Capacity : 2017/1991

Chassis No : WDD2054422F486020 Engine No : 27492030901694

: 57681 Mileage Colour : White

2. TYRES CONDITION

			Size	<u>Made</u>	Balance		Rim
FRONT	O/S	:	225/40 R17	Delinte	7.00	mm	Sport
REAR	O/S	:	225/35 R19	Michelin	7.00	mm	Sport
FRONT	N/S	:	225/40 R17	Delinte	7.00	mm	Sport
REAR	N/S	:	225/35 R19	Michelin	7.00	mm	Sport



No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front n/s portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : U2 Spray Painting Pte Ltd

No.25 Kaki Bukit Road 4 #06-43 Synergy@KB Singapore 417800

5. Estimated normal period of repair : 4 working days to complete.

6. Enclosed number of photograph : 53 copies.

7. In accordance to your instruction, we have <u>Not Authorised</u> repair to the vehicle and the survey was done on a <u>"Without Prejudice"</u> basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SJV 7171 J

Report No:

TP/ 12-19008/DY / 2019

SPARE PARTS

SPAR	EFANIS				
Qty	Parts Description	Condition	rkshop's timation	Our Revised Estimation	
	Nett Items				
1	Front headlamp	Damage	\$ 4535.00	\$	4535.00
1	Front bumper	Damage	\$ 1700.00	\$	1700.00
1	Front bumper sensor (1pc)	Damage	\$ 275.00	\$	275.00
1	Front shock absorber	Intact	\$ 510.00	\$	
1	Front knuckle arm	Intact	\$ 730.00	\$	
1	Front lower arm	Intact	\$ 530.00	\$	
2	Steering tire rod ends	Damage	\$ 402.00	\$	402.00
2	Steering ball heads	Damage	\$ 392.00	\$	392.00
			\$ 9074.00	\$	7304.00
	Special Nett Items				
1	Front bumper sticker	Damage	\$ 380.00	\$	380.00
1	Front tyre (Depreciation)	Damage	\$ 400.00	\$	200.00
1	Front sport rim (1 set)	Damage	\$ 1800.00	_\$_	1800.00
			\$ 2580.00	\$	2380.00

Vehicle No:

SJV 7171 J

Report No:

TP/ 12-19008/DY / 2019

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation		Our Revised Estimation	
	Spare Parts Total c/f	\$	11654.00	\$	9684.00
1	To provide towing service charge.	\$	60.00	\$	60.00
2	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$	80.00	\$	40.00
3	To remove and refit front undercarriage.	\$	400.00	\$	200.00
4	To check and re-adjust (Computerized) all wheel alignment.	\$	120.00	\$	120.00
5	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and wield body panels. To re-adjust to the original position using power tools.	\$	500.00	\$	250.00
6	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$	500.00	\$	250.00
	Total	\$	13314.00	\$	10604.00

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 8500.00

SDLS: EIGHT THOUSAND FIVE HUNDRED ONLY

Qualified Appraiser