

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20008108/EQF3E2

Date: 18/08/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713

Claimant Vehicle No : SJY5616R

Insured Vehicle No : SMC1702G

Date of Loss: 03/08/2020

Nature of Claim: TP Claim No: 626865

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY5616R**

Make &amp; Model: AUDI A4, 2.0 TFSI QU S-TRONIC (A)

Engine No: CDN137363

Reg. Date: 14/09/2010 (Man. Year: 2010)

Chassis No: WAUZZZ8K9BA016215

Colour: Grey

Odometer: 193363 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 245/40 R18

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,393.00	4,280.00	10,113.00	70.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,510.00	1,220.00	2,290.00	65.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,903.00</b>	<b>5,500.00</b>	<b>12,403.00</b>	<b>69.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>17,903.00</b>	<b>4,400.00</b>	<b>13,503.00</b>	<b>75.42</b>

### INSPECTION

Date of Assignment: 05/08/2020

Date Inspected: 07/08/2020 Inspected At:

Auburn Auto Pte Ltd (HQ)  
176 SIN MING DRIVE, #04-18 SIN MING  
AUTOCARE  
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 18 Aug 2020)
<b>Parts:</b>	143	AUDI A4 2.0 TFSI QU S-TRONIC (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJY5616R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,800.00 F	*1,656.00 FL
2	1		*REAR TAILLAMP (LH)	Broken	1,500.00 F	*680.00 FL
3	2		*REAR L/H & R/H HEAD LIGHT	Not Necessary	1,500.00 F	*- FL
4	1		*REAR TAILGATE MECHANISM	Not Necessary	800.00 F	*- FL
5	1		*REAR TAILGATE LOCK	Not Necessary	480.00 F	*- FL
6	1		*REAR BUMPER	Deformed	1,200.00 F	*1,200.00 FL
7	1		*REAR BUMPER SIDE RETAINERS	Broken	428.00 F	*100.00 FL
8	1		*BUMPER SENSOR (LH)	Shorted	320.00 F	*245.00 FL
9	1		*REAR BUMPER REFLECTORS	Not Necessary	350.00 F	*- FL
10	1		*REAR BUMPER TOP STEP GARNISH	Not Necessary	320.00 F	*- FL
11	1		*REAR END PANEL	Repair	1,800.00 F	*- FL
12	1		*REAR END PANEL INNER GARNISH	Not Necessary	580.00 F	*- FL
13	1		*REAR BOOT GARNISH	Not Necessary	380.00 F	*- FL
14	1		*HYDRAULIC HINGE	Not Necessary	200.00 F	*- FL
15	2		*RUBBER MOULDING	Not Necessary	120.00 F	*- FL
16	1		*NUMBER PLATE	Not Necessary	120.00 F	*- FL
17	1		*REAR REVERSE CAMERA	Not Necessary	320.00 F	*- FL
18	1		*REAR TAILGATE AUDI EMBLEM	Necessary	160.00 F	*86.00 FL
19	1		*REAR TAILGATE A4 EMBLEM	Necessary	160.00 F	*73.00 FL
20	1		*REAR TAILGATE 2.0T EMBLEM	Necessary	140.00 F	*60.00 FL
21	1		*SPARE TYRE TOP BOARD	Not Necessary	290.00 F	*- FL
22	1		*REAR BUMPER REINFORCEMENT UNIT (LOWER SPOILER)	Cut	655.00 F	*600.00 FL
23	1		*BACK BUMPER CLIP	Necessary	150.00 FS	*50.00 FS
24	1		*SET REAR REVERSE SENSOR	Repeated	620.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 14,393.00 4,750.00**  
**- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 470.00**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					<b>Total Parts (S\$)</b>	<b>14,393.00</b>
						<b>4,280.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REMOVE AND REFIT REAR TAILGATE	New	300.00	200.00
2	REMOVE AND REFIT REAR BUMPER	New	300.00	200.00
3	REMOVE AND REFIT REAR PANEL	New	800.00	100.00
4	REMOVE, REFIT AND REPLACED DAMAGE LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	150.00	30.00
5	REMOVE AND REFIT INNER GARNISHES TRIM TO ASSIST REPAIR	New	200.00	30.00
6	REMOVE AND REFIT REAR REVERSE SENSOR	New	240.00	30.00
7	TO APPLY UNDERCOATING ON REPLACED PANEL	New	120.00	30.00
8	TO RESPRAY PAINTING	New	1,400.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>3,510.00</b>	<b>1,220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >