

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20008110/BVF3E2

Date: 04/09/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19370919000
Claimant Vehicle No :	GBH6197K	Insured Vehicle No :	YN9450E
Date of Loss:	04/08/2020	Nature of Claim:	TP
		Claim No:	SNM20D202737/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH6197K	Engine No:	10JBHW3019110
Make & Model:	CITROEN BERLINGO, 1.6 HDI (M)	Chassis No:	VF77FBHYMHJ758452
Reg. Date:	01/08/2018 (Man. Year: 2017)	Odometer:	72908 km
Colour:	Grey		
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Kleber 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Kleber 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,063.64	7,135.46	6,928.18	49.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,680.00	1,490.00	2,190.00	59.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,743.64	8,625.46	9,118.18	51.39
Approved Total (Overridden) (S\$)		6,900.00		
Nett Amount (S\$)	17,743.64	6,900.00	10,843.64	61.11

INSPECTION

Date of Assignment:	06/08/2020	Inspected At:	Team Autopro Pte Ltd (Sin Ming)
Date Inspected:	06/08/2020		160 SIN MING DR
			#01-14 SIN MING AUTO CITY
			SINGAPORE 575722
Estimated Period of Repair:	7.0 days		

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Sep 2020)
Parts:	M1-MPV	CITROEN BERLINGO 1.6 HDI (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH6197K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (TOP)	Dented	336.67 FL	*336.67 FL
2	1		*FRONT BUMPER (CENTRE)	Broken	610.00 FL	*610.00 FL
3	1		*FRONT BUMPER (BOTTOM)	Broken	687.90 FL	*245.00 FL
4	1		*FRONT BUMPER TOW COVER	No such part	65.00 FL	*- FL
5	2		*FRONT BUMPER FOG LAMP COVER	Broken	373.20 FL	*260.00 FL
6	2		*FRONT BUMPER FOG LAMP	Broken	750.40 FL	*750.40 FL
7	2		*FRONT BUMPER FOG LAMP BRACKET	No such part	316.40 FL	*- FL
8	2		*FRONT BUMPER SIDE RETAINER	Necessary	172.80 FL	*172.80 FL
9	1		*FRONT BUMPER SPONGE (TOP)	No such part	190.00 FL	*- FL
10	1		*FRONT BUMPER SPONGE (BOTTOM)	No such part	196.00 FL	*- FL
11	2		*FRONT BUMPER SIDE BRACKETS	No such part	237.20 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Dented	688.63 FL	*465.00 FL
13	1		*FRONT GRILLE	Broken	668.90 FL	*560.00 FL
14	2		*FRONT GRILLE MOULDING	Broken	652.40 FL	*368.00 FL
15	1		*FRONT LOWER GRILLE	Broken	548.60 FL	*396.00 FL
16	1		*BONNET	Dented	2,928.00 FL	*1,065.00 FL
17	1		*BONNET INNER LOCK	Not Damaged	228.60 FL	*- FL
18	2		*HEADLAMP	Broken	2,577.20 FL	*2,577.20 FL
19	2		*HEADLAMP LOWER BRACKET	No such part	562.00 FL	*- FL
20	1		*SUPPORT PANEL	Not Damaged	980.50 FL	*- FL
21	1		*SUPPORT PANEL SIDE AIR DUCT	Not Damaged	158.80 FL	*- FL
22	1		*SUPPORT PANEL CENTRE GARNISH	Not Damaged	346.60 FL	*- FL
23	2		*SUPPORT PANEL BOTTOM SIDE BRACKET	Not Damaged	235.20 FL	*- FL
24	1		*SUPPORT PANEL BOTTOM CENTRE PANEL	Not Damaged	148.60 FL	*- FL
25	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
26	1		*FRONT BUMPER (TOP) CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*FRONT BUMPER (CENTRE) CLIPS	No such part	50.00 FS	*- FS
28	1		*FRONT BUMPER (BOTTOM) CLIPS	No such part	50.00 FS	*- FS
29	2		*FRONT BUMPER FOG LAMP COVER CLIPS	No such part	100.00 FS	*- FS
30	1		*FRONT GRILLE CLIPS	No such part	50.00 FS	*- FS
31	1		*FRONT LOWER GRILLE CLIPS	No such part	50.00 FS	*- FS
32	1		*FRONT BONNET SEALANT	Necessary	100.00 FS	*30.00 FS
33	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
34	1		*FRONT NO PLATE W/CASING	Bent	80.00 FS	*50.00 FS
35	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
36	1		*A/C FLUID	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,529.60	7,916.07
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,465.96	780.61

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	14,063.64	7,135.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R RADIATOR	New	150.00	0.00
2	R&R A/C CONDENSER	New	150.00	0.00
3	UPHOLSTERY	New	300.00	0.00
4	CHECK WIRING	New	80.00	30.00
5	RUST PROOFING	New	200.00	60.00
6	PANEL BEAT	New	1,400.00	800.00
7	SPRAY PAINTING	New	1,400.00	600.00
Gross Labour Cost (S\$)			3,680.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >