

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Aug 2020 Edit Reg		05 Aug 2020 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

[Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	-, Co. Reg. No.: -		
Vehicle Reg. No.:	FBK6690L	Date of Loss:	26/07/2020 00:00 - :59 [55 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT20070350	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHA3721H	Policy No. (Claimant):	
		Excess:	
Repairer:	Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb, 417800 Kaki Bukit - Tel: 63846939 / 90113391		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 17/08/2020]		

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBK6690L (MCT20070350)**
[SHA3721H]

TP

-

Jul 26 2020 12:00AM

[-]

Equator Brotherhood

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/08/20 19:02	General View	 Load JPG	
2	05/08/20 19:02	General View	 Load JPG	
3	05/08/20 19:02	General View	 Load JPG	
4	05/08/20 19:02	General View	 Load JPG	
5	05/08/20 19:02	General View	 Load JPG	
6	05/08/20 19:02	General View	 Load JPG	
7	05/08/20 19:02	General View	 Load JPG	
8	05/08/20 19:02	General View	 Load JPG	
9	05/08/20 19:02	General View	 Load JPG	
10	05/08/20 19:02	General View	 Load JPG	
11	05/08/20 19:02	General View	 Load JPG	
12	05/08/20 19:02	General View	 Load JPG	
13	05/08/20 19:02	General View	 Load JPG	
14	05/08/20 19:02	General View	 Load JPG	
15	05/08/20 19:02	General View	 Load JPG	
16	05/08/20 19:02	General View	 Load JPG	
17	05/08/20 19:02	General View	 Load JPG	
18	05/08/20 19:02	General View	 Load JPG	
19	05/08/20 19:02	General View	 Load JPG	
20	05/08/20 19:02	General View	 Load JPG	
21	05/08/20 19:02	General View	 Load JPG	
22	05/08/20 19:02	General View	 Load JPG	
23	05/08/20 19:02	General View	 Load JPG	
24	05/08/20 19:02	General View	 Load JPG	
25	05/08/20 19:02	General View	 Load JPG	
26	05/08/20 19:02	General View	 Load JPG	
27	05/08/20 19:02	General View	 Load JPG	
28	05/08/20 19:02	General View	 Load JPG	
29	05/08/20 19:02	General View	 Load JPG	
30	05/08/20 19:02	General View	 Load JPG	
31	05/08/20 19:02	General View	 Load JPG	
32	05/08/20 19:02	General View	 Load JPG	
33	05/08/20 19:02	General View	 Load JPG	
34	05/08/20 19:02	Odometer Reading	 Load JPG	
35	05/08/20 19:02	General View	 Load JPG	
36	05/08/20 19:02	General View	 Load JPG	
37	05/08/20 19:02	General View	 Load JPG	
38	05/08/20 19:02	General View	 Load JPG	
39	05/08/20 19:02	General View	 Load JPG	
40	05/08/20 19:02	Chassis Number	 Load JPG	

Photos/Images			3 per page ▾		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
41	05/08/20 19:02	Chassis Number		Load JPG	☒
42	05/08/20 19:02	General View		Load JPG	☒
43	05/08/20 19:02	General View		Load JPG	☒
44	05/08/20 19:02	General View		Load JPG	☒
45	05/08/20 19:02	General View		Load JPG	☒
46	05/08/20 19:02	General View		Load JPG	☒
47	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
48	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
49	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
50	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
51	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
52	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
53	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
54	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
55	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
56	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
57	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
58	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
59	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
60	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
61	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
62	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
63	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
64	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
65	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
66	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
67	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
68	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
69	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
70	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
71	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
72	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
73	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
74	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
75	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
76	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
77	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
78	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
79	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
80	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
81	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
82	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
83	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
84	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
85	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
86	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
87	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
88	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
89	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
90	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
91	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
92	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
93	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒

Photos/Images			3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
94	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
95	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
96	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
97	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
98	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
99	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
100	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
101	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
102	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
103	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
104	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
105	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
106	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
107	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
108	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
109	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
110	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
111	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
112	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
113	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
114	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
115	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
116	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
117	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
118	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
119	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
120	03/09/20 17:35	Photographs of Damaged Parts		Load JPG	☒
Documentation			1 per page		☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	06/08/20 08:31	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III20008115/ETF3S2**Date:** 23/09/2020**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	FBK6690L	Insured Vehicle No :	SHA3721H
Date of Loss:	26/07/2020	Nature of Claim:	TP
		Claim No:	MCT20070350

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBK6690L	Engine No:	2PB2002653
Make & Model:	YAMAHA YZF-R15, 150cc (M)	Chassis No:	ME1KG0690G2001868
Reg. Date:	16/12/2015 (Man. Year: 2015)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	190/50 R17	Rear Tyre Size:	150/50 R17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	05/08/2020	
Date Inspected:	05/08/2020	Inspected At: Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb Singapore 417800
Estimated Period of Repair:	0.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Sep 2020)	
Parts:	N/A	YAMAHA YZF-R15 150cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK6690L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >