

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20008119/R1SF3E2

**Date:** 16/12/2020

### REFERENCE

Insured/Claimant:	CHAN MOY JIN	Policy No:	1700063167		
Date of Loss:	07/07/2020	Nature of Claim:	OD	Claim No:	7305348924SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT235S		
Make & Model:	AUDI A1, 999cc SB 1.0 TFSI (PI) (A)	Engine No:	CHZ507976
Reg. Date:	14/10/2017 (Man. Year: 2017)	Chassis No:	WAUZZZ8X8JB013259
Colour:	Grey	Odometer:	21696 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$69,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/45R16	Rear Tyre Size:	215/45R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,290.00	4,322.40	1,967.60	31.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,182.00	4,582.00	5,600.00	55.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,472.00</b>	<b>8,904.40</b>	<b>7,567.60</b>	<b>45.94</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	15,872.00	8,304.40	7,567.60	47.68
<b>+ GST 7.00/7.00% (S\$)</b>	1,111.04	581.31	529.73	47.68
<b>Nett Amount (S\$)</b>	<b>16,983.04</b>	<b>8,885.71</b>	<b>8,097.33</b>	<b>47.68</b>

### INSPECTION

Date of Assignment:	06/08/2020		
Date Inspected:	05/08/2020	Inspected At:	281 ALEXANDRA RD Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	7.0 days		

**Adjuster:** MOHD RASUL

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-LH	Bent	1,915.00 FS	*1,532.00 FS
2	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	126.00 FS	*- FS
3	1		*FRONT DOOR CATCH	Bent	84.00 FS	*66.88 FS
4	1		*EXTERIOR MIRROR MOUNTING-LH	Scratched	434.00 FS	*363.60 FS
5	1		*EXTERIOR DOOR HANDLE	Repair	146.00 FS	*- FS
6	1		*DOOR HANDLE CAP	Repair	28.00 FS	*- FS
7	1		*REAR DOOR-LH	Bent	1,915.00 FS	*1,607.20 FS
8	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	79.00 FS	*- FS
9	1		*REAR DOOR HINGE-LH UPPER	Serviceable	143.00 FS	*- FS
10	1		*REAR DOOR HINGE-LH LOWER	Serviceable	125.00 FS	*- FS
11	1		*REAR DOOR CATCH	Serviceable	84.00 FS	*- FS
12	1		*AIRBAG STICKER	Not Necessary	23.00 FS	*- FS
13	1		*REAR ALUMINIUM RIM-LH	Scratched	666.00 FS	*532.40 FS
14	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
15	1		*SUNDRIES	Necessary	300.00 FS	*6.88 FS
16	1		*LHS REAR FENDER STONE CHIP GUARD FOIL	Necessary	42.00 FS	*33.44 FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (S\$)</b>	<b>6,290.00      4,322.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE LHS FRONT DOOR PANEL TRIM.TO REMOVE AND RENEW LHS WING MIRROR ASSY	New	350.00	0.00
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	560.00	560.00
3	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR.TO REPAIR LHS SILL PANEL,LHS B-PILLAR,DOOR ENTRANCE AND LHS REAR FENDER.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,500.00	1,250.00
4	TO RESPRAY LHS FRONT DOOR,LHS REAR DOOR,LHS B-PILLAR,LHS SILL PANEL,DOOR HANDLE,DOOR ENTRANCE,HINGES AND LHS REAR FENDER	New	5,300.00	2,300.00
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,182.00</b>	<b>4,582.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >