

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20008120/AVF3E2

Date: 05/02/2021

REFERENCE

Insured/Claimant:	THAW TINT	Policy No:	1700065489	Claim No:	1470887263SG
Date of Loss:	03/08/2020	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT258B	Engine No:	CVK047182
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Chassis No:	WAUZZZF51JA034302
Reg. Date:	13/10/2017 (Man. Year: 2017)	Odometer:	73019 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$130,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,020.00	14,448.88	6,571.12	31.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,072.00	5,142.00	2,930.00	36.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,092.00	19,590.88	9,501.12	32.66
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	28,292.00	18,790.88	9,501.12	33.58
+ GST 7.00/7.00% (S\$)	1,980.44	1,315.36	665.08	33.58
Nett Amount (S\$)	30,272.44	20,106.24	10,166.20	33.58

INSPECTION

Date of Assignment:	06/08/2020		
Date Inspected:	05/08/2020	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	8.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,251.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	402.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	70.00 FS	-
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	225.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	62.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	468.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	36.00 FS	*28.48 FS
8	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	123.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	795.00 FS	*- FS
10	1		*FRONT PARKING AID SENSOR - FRONT OUTER (NPA)	Not Necessary	0.00 FS	*- FS
11	1		*FRONT FENDER - RH	Dented	1,048.00 FS	*838.40 FS
12	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	53.00 FS	*- FS
13	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	73.00 FS	*- FS
14	1		*FRONT FENDER BRACKET - RH	Not Necessary	35.00 FS	*- FS
15	1		*FRONT FENDER BRACE - RH	Bent	117.00 FS	*93.60 FS
16	1		*DEFORMATION ELEMENT BRACKET - RH	Not Necessary	49.00 FS	*- FS
17	1		*FRONT FENDER BRACKET	Not Necessary	35.00 FS	*- FS
18	1		*TOP FENDER LEDGE COVER - UPPER	Not Necessary	35.00 FS	*- FS
19	1		*TOP FENDER LEDGE COVER - LOWER	Not Necessary	16.00 FS	*- FS
20	1		*FRONT FENDER TRIM - RH	Necessary	157.00 FS	*125.60 FS
21	1		*WHEEL HOUSING LINER - RH	Deformed	272.00 FS	*217.20 FS
22	1		*WHEEL SPOILER	Torn	73.00 FS	*57.76 FS
23	1		*WHEEL SPOILER TRIM - RH	Not Necessary	36.00 FS	*- FS
24	1		*STONE CHIP GUARD - RH	Necessary	50.00 FS	*39.92 FS
25	1		*LED HEADLIGHT - RH	Cut	7,812.00 FS	*6,249.60 FS
26	1		*LIFT CYLINDER - RH	Not Necessary	196.00 FS	*- FS
27	1		*FRONT ALUMINIUM RIM - RH	Cut	1,012.00 FS	*809.60 FS
28	1		*FRONT WISHBONE LINK - RH	Bent	533.00 FS	*426.00 FS
29	1		*FRONT SUSPENSION GUIDE - RH	Bent	932.00 FS	*745.60 FS
30	1		*FRONT UPPER CONTROL ARM - RH	Bent	506.00 FS	*404.40 FS
31	1		*REAR UPPER CONTROL ARM - RH	Bent	506.00 FS	*404.40 FS
32	1		*WHEEL BEARING HOUSING - RH	Damaged	957.00 FS	*765.20 FS
33	1		*SWIVEL JOINT	Bent	191.00 FS	*152.80 FS
34	1		*WHEELHUB	Damaged	790.00 FS	*371.60 FS
35	1		*TIE ROD END - RH	Bent	195.00 FS	*155.60 FS
36	1		*SUNDRIES	Necessary	300.00 FS	*276.40 FS
37	1		*FRONT WHEEL BEARING RHS (Supplementary)	Damaged	239.00 FS	*191.20 FS
38	1		*SUSPENSION FORKS RHS (Supplementary)	Bent	261.00 FS	*208.40 FS
39	1		*TIE ROD RHS (Supplementary)	Bent	98.00 FS	*78.00 FS
40	1		*CLAMP (Supplementary)	Necessary	11.00 FS	*8.32 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 21,020.00 14,448.88

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & TRANSFER / REINSTALL FRONT BUMPER WIRE HARNESS FOR FRONT PARKING AID SYSTEM	New	280.00	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT. AND POWER MODULE. TO CARRY OUT CALIBRATION	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,200.00	1,100.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO DISMANTLE, INSPECT AND RENEW RHS FRONT SUSPENSION ASSY	New	1,800.00	1,800.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO CARRY OUT PRE-WHEEL ALIGNMENT AND POST-WHEEL ALIGNMENT. TO RENEW RHS FRONT RIM (Supplementary)	New	520.00	240.00
Gross Labour Cost (\$\$)			8,072.00	5,142.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >