## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

1	22/08/20	3P INSURANCE: _	NTUC
	03/08/20	CUDVEYOR.	LKK
MODEL:	HYUNDAI I 40	SURVEYOR: _	LKK
	SHA2311P	MVA: _	OLIVIA
VEH NO	Bull to the December of the Control		

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS	1. /
CAN THE RESERVE OF THE PERSON AND ADDRESS OF THE PERSON ADDRESS OF THE PERSO	Rear Bumper	1		\$1,106.00	de/
	Rear Bumper Under Cover	1		\$228.00	/ ^
	Rear Bumper Reflector Lamp(RH)	1		\$31.90	1 / 1 X
	Rear Bumper Reinforcement Bracket (RH)	1		\$80.30	7 (
	Rear Bumper Reinforcement	1		\$428.40	11-5
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00	
	Rear Bumper Side Bracket (RH)	1		\$35.60	710
	Rear Bumper Sponge	1		\$119.50	X"
	SPARE PARTS SUB TOTAL LESS 20%	1		<b>\$2,051.70</b> \$410.34	1391.60 1113.28
	DISCOUNTED SPARE PARTS TOTAL			\$1,641.36	<b>-</b>
	Rear Bumper Rubber Mat	1		\$50.00	Nett
	Rear Bumper Reverse Sensor	1		nu/ \$135.70	Nett '
the Repair  To resurve  To display  Parts price  Third party  No illegal r  Supplements subject t	Consultants hence notify  ref of the following:  y taifore/after spray painting de haged part(s) during resurvey is are subject to confirmation is livey is on a "Without Prejudice" basis indication(s) is allowed in ref item(s) must be resurveyed and to that approval from Insurance Company SPARE PARTS & NETT TOTA  SPARE PARTS & NETT TOTA	1		\$185.70 \$1,827.06	] 185.70,
	Panel Beating			\$900.00	280
	Spray Painting			\$500.00	200
	Remove/Refix Reverse Sensor  Tanfin 97445749  WY 4/8/20 & 3pm LABOUR TOTA  LABOUR TOTA  LABOUR TOTA	AL		\$120.00 \$1,520.00	510
	limin after report ESTIMATE TOTAL  fulthic Marylongar Mucho. 10			\$3,347.06	1808.98
This is ar prepared	n initial estimate based on a visual inspection of the abo after the vehicle is surveyed by a motor Surveyor appoi	ve vehic nted by	ie. The final rep the insurance co	pair quantum will ompany.	60 4/58 1450 2800