

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC20008124/T1vf3e2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	17-08-2020 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SKN 9821J	Veh. Inspected		SHC 1997G	
	Policy No.	5104343478-02	Coverage (\$)		0.00	
	Claim No.	MT/1099562-001	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	05/08/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	KMHLB41UMHU100074	Colou	r	BLUE	
	Odometer	299480	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	HANKC	OOK	6 mm	
	L/H Front Tyre	205/60 R16	HANKC	OOK	6 mm	
	R/H Rear Tyre	205/60 R16	HANKC		6 mm	
	L/H Rear Tyre	205/60 R16	HANKC		6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	05/08/2020	Inspec	tion Date	05/08/2020	
	Survey held at	eld at COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					