

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20008130/ASF3E2

Date: 26/11/2020

REFERENCE

Insured/Claimant:	POH KEE BOON	Policy No:	1800116420	
Date of Loss:	03/08/2020	Nature of Claim:	OD	Claim No: 8641981714SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ33K		
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Engine No:	CYR065575
Reg. Date:	28/09/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ4M1JD048449
Colour:	Green	Odometer:	14276 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$198,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55R19	Rear Tyre Size:	255/55R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,804.00	8,048.32	7,755.68	49.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,762.00	4,032.00	5,730.00	58.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,566.00	12,080.32	13,485.68	52.75
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	25,066.00	11,580.32	13,485.68	53.80
+ GST 7.00/7.00% (S\$)	1,754.62	810.62	944.00	53.80
Nett Amount (S\$)	26,820.62	12,390.94	14,429.68	53.80

INSPECTION

Date of Assignment:	06/08/2020		
Date Inspected:	06/08/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER-LH	Repair	1,602.00 FS	*- FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	75.00 FS	*- FS
3	1		*FRONT FENDER WHEEL ARCH TRIM-LH/RH	N/s Necessary	654.00 FS	*261.20 FS
4	1		*FRONT DOOR-LH	Dented	3,937.00 FS	*3,149.60 FS
5	1		*FRONT DOOR OUTER SEAL	Necessary	250.00 FS	*200.00 FS
6	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
7	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
8	1		*FRONT DOOR CATCH	Not Necessary	127.00 FS	*- FS
9	1		*FRONT DOOR COVER-LH	Cut	447.00 FS	*357.20 FS
10	1		*REAR DOOR-LH	Dented	3,937.00 FS	*3,149.60 FS
11	1		*REAR DOOR OUTER SEAL-LH	Necessary	247.00 FS	*197.60 FS
12	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
13	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
14	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	97.00 FS	*- FS
15	1		*REAR DOOR CATCH	Not Necessary	104.00 FS	*- FS
16	1		*REAR DOOR COVER-LH	Cut	593.00 FS	*474.00 FS
17	1		*EXTERIOR MIRROR MOUNTING-LH	Not Necessary	1,491.00 FS	*- FS
18	1		*REAR DOOR WHEEL ARCH TRIM-LH	Necessary	121.00 FS	*96.40 FS
19	1		*REAR FENDER WHEEL ARCH TRIM-LH	Not Necessary	194.00 FS	*- FS
20	1		*REAR ALUMINIUM RIM-LH	Repair	1,215.00 FS	*- FS
21	1		*SUNDRIES	Necessary	300.00 FS	*11.52 FS
22	1		*REAR DOOR OUTER SEAL LHS	Necessary	189.00 FS	*151.20 FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	15,804.00 8,048.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER/REINSTALL FRONT BUMPER WIRE HARNESS FOR FRONT PARKING AID SYSTEM	New	280.00	0.00
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	560.00	560.00
3	TO DISMANTLE LHS FRONT DOOR PANEL TRIM.TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	New	450.00	0.00
4	TO DISMANTLE FRONT BUMPER.TO RENEW LHS FRONT FENDER,LHS FRONT DOOR AND LHS REAR DOOR.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,000.00	1,200.00
5	TO RESPRAY LHS FRONT FENDER,LHS FRONT DOOR AND LHS REAR DOOR	New	4,000.00	1,800.00
6	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			9,762.00	4,032.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >