

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20008131/EGS3Q2

Date: 16/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SDB8820P	Insured Vehicle No :	SHD4254S
Date of Loss: 01/08/2020	Nature of Claim: TP	Claim No: MCT20080026

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDB8820P		
Make & Model:	HONDA CIVIC, 1.6 VTI (A)	Engine No:	R16A11000829
Reg. Date:	03/01/2007 (Man. Year: 2006)	Chassis No:	JHMF46206S200732
Colour:	Black	Odometer:	240459 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,255.04	2,341.84	3,913.20	62.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	1,480.00	1,770.00	54.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,505.04	3,821.84	5,683.20	59.79
Approved Total (Overridden) (\$\$)		3,050.00		
Nett Amount (\$\$)	9,505.04	3,050.00	6,455.04	67.91
+ Car Rental (8.0 x S\$100.00/day) (\$\$)		800.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,857.45		
Global Sum Settlement (\$\$)		3,850.00		

INSPECTION

Date of Assignment:	06/08/2020	
Date Inspected:	06/08/2020 Inspected At:	My Car Consultant Pte Ltd - Ubi (HQ) 53 Ubi Ave 1, #01-33 Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Sep 2020)
Parts:	143	HONDA CIVIC 1.6 VTI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDB8820P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	987.00 FL	*657.00 FL
2	1		*BOOT LID LOCK	Bent	312.00 FL	*191.80 FL
3	1		*BOOT LID WEATHERSTRIP	Crushed	198.00 FL	*198.00 FL
4	1		*BOOT LID LOGO	Necessary	68.00 FL	*68.00 FL
5	1		*BOOT LID EMBLEM CIVIC	Necessary	45.00 FL	*45.00 FL
6	1		*BOOT LID EMBLEM IVETC	Necessary	48.00 FL	*48.00 FL
7	1		*REAR BUMPER	Dented	648.00 FL	*648.00 FL
8	1		*REAR BUMPER TOP BEAM	Not Necessary	145.00 FL	*- FL
9	2		*REAR BUMPER SIDE RETAINER	Broken	112.00 FL	*112.00 FL
10	2		*REAR BUMPER BRACKET	Not Necessary	32.00 FL	*- FL
11	2		*TAILAMP	Not Necessary	1,114.80 FL	*- FL
12	2		*TAILAMP LOWER BRACKET	Not Necessary	64.00 FL	*- FL
13	1		*REAR END PANEL	Dented	436.00 FL	*436.00 FL
14	1		*REAR END PANEL TOP GARNISH	Crushed	186.00 FL	*186.00 FL
15	1		*REAR FENDER INNER TRIM RH	Not Necessary	580.00 FL	*- FL
16	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	312.00 FL	*- FL
17	1		*REAR EXHAUST PIPE	Not Necessary	1,025.00 FL	*- FL
18	2		*REAR EXHAUST MOUNTING	Not Necessary	56.00 FL	*- FL
19	1		*SET REAR REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
20	1		*SET REAR REVERSE CAMERA	Not Necessary	300.00 FS	*- FS
21	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
22	1		*SET REAR END PANEL GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
23	1		*FLOOR PANEL SEALANT	Not Necessary	150.00 FS	*- FS
24	1		*END PANEL SEALANT	Necessary	150.00 FS	*30.00 FS
25	1		*MISCELLANEOUS	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,528.80	2,859.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,273.76	517.96
Total Parts (\$\$)	6,255.04	2,341.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT REVERSE SENSOR	New	150.00	30.00
3	REMOVE AND REFIX REAR UPHOLSTERY	New	200.00	0.00
4	REMOVE AND REFIX EXHAUST SYSTEM	New	150.00	0.00
5	CHECK AND TEST FOR WATER LEAKAGE	New	50.00	30.00
6	REMOVE AND TRANSFER ALL BOOTLID MECHANISM	New	100.00	30.00
7	CHECK AND RESET FAULT CODE LIGHT ON	New	200.00	30.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	30.00
9	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
10	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	700.00
Gross Labour Cost (\$\$)			3,250.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >