

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20008143/UGA3Q2

Date: 14/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJM2482S	Insured Vehicle No :	SHC2001Z
Date of Loss: 05/08/2020	Nature of Claim: TP	Claim No: MCT20080053

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM2482S		
Make & Model:	MERCEDES-BENZ C180K, 1.8 (A)	Engine No:	27195231126131
Reg. Date:	26/12/2008 (Man. Year: 2008)	Chassis No:	WDD2040462A221890
Colour:	Black	Odometer:	327235 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,106.24	7,395.54	6,710.70	47.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,790.00	1,920.00	870.00	31.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,896.24	9,315.54	7,580.70	44.87
Approved Total (Overridden) (\$\$)		7,400.00		
Nett Amount (\$\$)	16,896.24	7,400.00	9,496.24	56.20
+ Loss of Use (6.0 x S\$100.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		8,007.45		
Global Sum Settlement (\$\$)		8,000.00		

INSPECTION

Date of Assignment:	05/08/2020	
Date Inspected:	06/08/2020	Inspected At: Super-zee Motor Service (HQ) BLK 14 DEFU LANE 10, #01-402 Singapore 539195

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2020)
Parts:	143	MERCEDES-BENZ C180K 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM2482S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deep Cut	1,655.70 FL	*1,465.12 FL
2	1		*REAR BUMPER MOULDING	Necessary	378.70 FL	*281.30 FL
3	1		*REAR FENDER RH	Repair	2,180.10 FL	*- FL
4	1		*REAR RH DOOR	Badly Dented / Bent	2,450.50 FL	*2,145.35 FL
5	1		*REAR RH DOOR MOULDING	Necessary	147.60 FL	*147.60 FL
6	1		*REAR RH DOOR REGULATOR	Not Necessary	792.60 FL	*- FL
7	1		*REAR RH DOOR REGULATOR MOTOR	Not Necessary	726.10 FL	*- FL
8	1		*REAR RH DOOR WEATHERSTRIP	Necessary	328.20 FL	*309.10 FL
9	1		*FRONT RH DOOR	Dented / Bent	2,090.40 FL	*2,090.40 FL
10	1		*FRONT RH DOOR MOULDING	Necessary	147.60 FL	*147.60 FL
11	1		*FRONT RH DOOR REGULATOR	Not Necessary	792.60 FL	*- FL
12	1		*FRONT RH DOOR REGULATOR MOTOR	Not Necessary	726.10 FL	*- FL
13	1		*FRONT RH DOOR WEATHERSTRIP	Necessary	328.20 FL	*310.10 FL
14	1		*RH SIDE SKIRT	Cut	636.30 FL	*636.30 FL
15	1		*REAR RH KNUCKLE ARM BEARING	Not Necessary	495.50 FL	*- FL
16	1		*REAR RH LOWER ARM	Not Necessary	245.60 FL	*- FL
17	1		*REAR RH CONTROL ARM	Not Necessary	286.20 FL	*- FL
18	1		*REAR RH SHOCK ABSORBER	Not Necessary	581.20 FL	*- FL
19	1		*REAR RH TYRE RIM	Cut	684.40 FL	*684.40 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	15,673.60	8,217.27
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,567.36	821.73
Total Parts (\$\$)	14,106.24	7,395.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANELBEAT WHERE NECESSARY	New	850.00	680.00
2	TO PUTTY ,APPLY PRIMER & SPRAYPAINT AFFECTED PORTION	New	1,300.00	980.00
3	TO APPLY RUSTPROOFING ON REPAIRED ,REPLACED PANEL	New	280.00	60.00
4	TO TRANSFER DOORS COMPONENTS	New	160.00	120.00
5	TO CHECK ELECTRICAL WIRING FUNCTIONS	New	80.00	20.00
6	COMPUTERISED WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (\$\$)			2,790.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >