

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008146/UEA3Q2

Date: 16/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900017549

Claimant
Vehicle No : GBF8982H **Insured Vehicle No :** SDL7733L

Date of Loss: 03/08/2020 Nature of Claim: TP Claim No: 0140704859SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF8982H		
Make & Model:	TOYOTA DYNA, 3.0 D (M)	Engine No:	1KD2622006
Reg. Date:	04/04/2017 (Man. Year: 2016)	Chassis No:	KDY2318025344
Colour:	Blue	Odometer:	93963 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R13 (D)
Front Left Side:	GREEN-MAX 5 mm	Rear Left Side:	GREEN-MAX 5/5 mm
Front Right Side:	GREEN-MAX 5 mm	Rear Right Side:	GREEN-MAX 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,112.26	3,746.58	2,365.68	38.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	2,240.00	2,080.00	48.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,432.26	5,986.58	4,445.68	42.61
Approved Total (Overridden) (\$\$)		4,800.00		
(\$\$)	10,432.26	4,800.00	5,632.26	53.99
+ GST 7.00/7.00% (\$\$)	730.26	336.00	394.26	53.99
Nett Amount (\$\$)	11,162.52	5,136.00	6,026.52	53.99
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 05/08/2020

Date Inspected: 06/08/2020 Inspected At:

Auto N Cars Services Pte Ltd (HQ)
Blk 1 Kaki Bukit Ave 6 #01-04,
AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	638.22 FL	*638.22 FL
2	1		*FRONT BUMPER BRACKET LH & RH	O/S Bent	187.00 FL	*93.50 FL
3	1		*FRONT BUMPER RH FOG LAMP	Cracked	198.00 FL	*198.00 FL
4	1		*FRONT BUMPER RH FOG LAMP COVER (NPA)	Grazed	0.00 FL	*- FL
5	1		*FRONT GRILLE	Cracked	407.00 FL	*407.00 FL
6	1		*FRONT BODY PANEL	Badly Dented	704.00 FL	*704.00 FL
7	1		*RH FRONT CORNER PANEL	Distorted	132.00 FL	*132.00 FL
8	6		*RH FRONT CORNER PANEL CLIPS	Not Necessary	3.50 FL	*- FL
9	1		*FRONT BODY PANEL TOP GARNISH	Cracked	88.00 FL	*88.00 FL
10	10		*FRONT BODY PANEL TOP GARNISH CLIPS	Not Necessary	3.50 FL	*- FL
11	1		*RH FRONT BODY PANEL CORNER GARNISH	Cracked	209.00 FL	*209.00 FL
12	10		*RH FRONT BODY PANEL CORNER GARNISH CLIPS	Not Necessary	3.50 FL	*- FL
13	1		*WIPER PANEL -CENTRE	Repair	209.00 FL	*- FL
14	1		*RH WIPER PANEL	Cracked	121.00 FL	*121.00 FL
15	1		*RH HEADLAMP	Cracked	726.00 FL	*726.00 FL
16	1		*RH HEADLAMP GARNISH	Torn	33.00 FL	*33.00 FL
17	1		*RH A PILLAR	Repair	407.00 FL	*- FL
18	1		*RH FRONT DOOR	Dented / Buckled	1,296.00 FL	*1,296.00 FL
19	1		*RH FRONT DOOR HINGE -TOP	Not Necessary	183.60 FL	*- FL
20	1		*RH FRONT DOOR HINGE -BOTTOM	Not Necessary	187.00 FL	*- FL
21	1		*RH FRONT DOOR CHECKER	Not Necessary	132.00 FL	*- FL
22	1		*RH FRONT DOOR WIRE HARNESS (NPA)	Not Necessary	0.00 FL	*- FL
23	1		*RH FRONT DOOR WEATHERSTRIP	Not Necessary	143.00 FL	*- FL
24	1		*RH FRONT DOOR INNER TRIM BOARD (NPA)	Not Necessary	0.00 FL	*- FL
25	1		*DASHBOARD ASSEMBLY	Not Necessary	990.00 FL	*- FL
26	1		*DASHBOARD REINFORCEMENT (NPA)	Not Necessary	0.00 FL	*- FL
27	1		*DASHBOARD INSTRUMENT PANEL (NPA)	Not Necessary	0.00 FL	*- FL
28	1		*ACCELARATOR PADDLE (NPA)	Not Necessary	0.00 FL	*- FL
29	1		*ACCELARATOR PADDLE BRACKET (NPA)	Not Necessary	0.00 FL	*- FL
30	1		*BRAKE PADDLE (NPA)	Not Necessary	0.00 FL	*- FL
31	1		*BRAKE PADDLE BRACKET (NPA)	Not Necessary	0.00 FL	*- FL
32	1		*BRAKE BOOSTER (NPA)	Not Necessary	0.00 FL	*- FL
33	1		*BRAKE BOOSTER PUMP (NPA)	Not Necessary	0.00 FL	*- FL
34	1		*BRAKE FLUID TANK (NPA)	Not Necessary	0.00 FL	*- FL
35	1		*CLUTCH PADDLE (NPA)	Not Necessary	0.00 FL	*- FL
36	1		*CLUTCH PADDLE BRACKET (NPA)	Not Necessary	0.00 FL	*- FL
37	1		*CLUTCH PUMP	Not Necessary	165.00 FL	*- FL
38	1		*FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
39	1		*RH WHEEL ARCH (NPA)	Repair	0.00 FL	*- FL
40	1		*RH STEP PANEL (NPA)	Repair	0.00 FL	*- FL
41	1		*RH FRONT DOOR COMPANY REG STICKER	Necessary	159.20 FS	*30.00 FS
42	1		*RH STEP PANEL TOP GARNISH (NPA)	Cracked	0.00 FL	*- FL
43	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
44	1		*BRAKE FLUID	Not Necessary	80.00 FS	*- FS
45	2		*SEALANT	Not Necessary	50.00 FS	*- FS
46	1		*SUNDRIES	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,545.52	4,675.72
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,433.26	929.14

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	6,112.26
						3,746.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK & STRAIGHTEN THE DAMAGED PANELS ,REMOVE & RENEW DAMAGED PARTS ,ADJUST & REALIGN THE SAME	New	1,800.00	1,000.00
2	TO CHECK ALL WIRING AND LIGHTING	New	80.00	20.00
3	TO RUST PROOF ALL AFFECTED AREAS	New	180.00	60.00
4	TO REMOVE AND RENEW ACCELERATOR ,BRAKE AND CLUTCH PADDLE	New	180.00	0.00
5	TO BLEED BRAKE SYSTEM	New	180.00	0.00
6	TO BLEED CLUTCH SYSTEM	New	180.00	0.00
7	TO DO WATER SEEPAGE AND WIND NOISE TEST	New	80.00	0.00
8	TO REMOVE AND RENEW INSTRUMENT DASHBOARD AND DASHBOARD ASSEMBLY TO RE-RUN AND RE-ROUTE WIRE HARNESS	New	360.00	160.00
9	TO REMOVE COOLING COIL ,WIRE HARNESS AND OTHER MECHANICAL PARTS TO ASSIST WORKLOAD	New	80.00	0.00
10	TO PUTTY AND SPRAY ALL AFFECTED AREAS	New	1,200.00	1,000.00
Gross Labour Cost (\$\$)			4,320.00	2,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >