Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20008151/UPS3Q2

Date: 15/10/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant **SJZ890S** Insured Vehicle No: SH9102M

Vehicle No:

Date of Loss: 03/08/2020 Nature of Claim: ΤP Claim No: MCT20080040

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SJZ890S** Reg No:

Make & Model: HONDA CR-V, 2.4 I-VTEC (A) Engine No: K24Z15617908 Reg. Date: 23/07/2010 (Man. Year: 2010) Chassis No: JHLRE4850AC204161 Odometer: 163509 km

Colour: Black

**Engine Capacity:** 2354 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

**General Condition:** Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

**CONDITION OF TYRES** 

Front Tyre Size: 255/50R19 Rear Tyre Size: 255/50R19 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50.00	10.00	40.00	80.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,390.00	1,210.00	46.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,650.00	1,400.00	1,250.00	47.17
+ GST 7.00/7.00% (S\$)	185.50	98.00	87.50	47.17
Nett Amount (S\$)	2,835.50	1,498.00	1,337.50	47.17
+ Loss of Use (2.0 x S	+ Loss of Use (2.0 x S\$100.00/day) (S\$)			
Nett Liability (S\$)		1,698.00		

**INSPECTION** 

05/08/2020 Date of Assignment:

Date Inspected: 25/08/2020 Inspected At: Kah Motor Co Sdn Bhd (Ubi)

15 Ubi Road 4

Singapore 408610

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Sep 2020)

Parts: M1-SUV HONDA CR-V 2.4 I-VTEC (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJZ890S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*SUNDRIES	Necessary	50.00 FS	*10.00 FS
F=Franchise part. S=SpcNett.				
		Total Parts (S\$)	50.00	10.00

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	STRAIGHTEN ALIGN RR R FENDER & RR R DOOR	New	1,400.00	350.00
2	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,200.00	1,040.00
	Gross Labour Cost (S\$)		2,600.00	1,390.00
	Report was unsubmitted durir	ng this print-out.		

< END OF ESTIMATES >