



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 4129R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BENT / CRACKED	666.00	666.00
1	FRONT BUMPER TOW COVER	DENTED	15.00	15.00
1	FRONT BUMPER REINFORCEMENT	BENT	130.00	130.00
2	FRONT BUMPER RETAINER @ \$20.00	O/S CRACKED	40.00	20.00
1	SET FRONT BUMPER LOWER SPOILER	TO REPAIR SEE LABOUR	1,600.00	-
1	FRONT BUMPER LOWER GRILLE	* CHECK	156.00	-
1	FRONT BUMPER RH FOG LAMP	* CHECK	274.00	-
1	FRONT BUMPER RH FOG LAMP COVER	DENTED	120.00	120.00
10	FRONT BUMPER CLIPS @ \$3.00	NECESSARY	30.00	30.00
1	FRONT GRILLE	DENTED	525.00	525.00
1	FRONT SUPPORT PANEL	* CHECK	999.00	-
1	RH HEAD LAMP	CRACKED	544.00	544.00
1	BONNET	BENT	681.00	681.00
1	FRONT RH FENDER	BENT	438.00	438.00
1	FRONT RH FENDER UNDER SHIELD	CRACKED	93.00	93.00
6	FRONT RH FENDER UNDER SHIELD CLIP @ \$3.00	NECESSARY	18.00	18.00
1	WASHER TANK	DENTED	67.00	67.00
1	FRONT RH SHOCK ABSORBER	* CHECK	428.00	-
1	FRONT RH KNUCKLE ARM	* CHECK	329.00	-
1	FRONT RH KNUCKLE BEARING	* CHECK	114.00	-
1	FRONT RH LOWER ARM	* CHECK	304.00	-
1	REAR BUMPER	MISSING	708.00	708.00
2	REAR BUMPER RETAINER @ \$26.00	NECESSARY	52.00	52.00
2	REAR BUMPER BRACKET @ \$20.00	* CHECK	40.00	-
10	REAR BUMPER CLIPS @ \$3.00	NECESSARY	30.00	30.00
1	REAR END PANEL	BENT	402.00	402.00
1	REAR END PANEL GARNISH	SERVICEABLE	70.00	-
2	TAIL LAMP @ \$276.00	O/S BROKEN	552.00	276.00
1	REAR BOOT LID	TO REPAIR SEE LABOUR	828.00	-

Report Ref No. CS/SMO20008156/Kvf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RH FENDER	BENT	723.00	723.00
1	REAR RH FENDER UNDER SHIELD	CRACKED	38.00	38.00
1	REAR ATTAGE EMBLEM	NECESSARY	38.00	38.00
1	REAR BOOT CENTRE EMBLEM	NECESSARY	41.00	41.00
1	MIVEC EMBLEM	NECESSARY	41.00	41.00
1	REAR EXHAUST SILENCER BOX	BENT	571.00	571.00
1	EXHAUST CENTRE PIPE	* CHECK	852.00	-
1	EXHAUST TAIL PIPE	* CHECK	742.00	-
2	EXHAUST MOUNTING @ \$24.00	TORN	48.00	48.00
1	REAR RH SHOCK ABSORBER	BENT	188.00	188.00
1	REAR RH WHEEL BEARING	NECESSARY	114.00	114.00
1	REAR AXLE	BENT	939.00	939.00
1	SPORT RIM	* CHECK	719.00	-
	LESS 20% DISCOUNT		-3,061.40	-1,511.20
			12,245.60	6,044.80
2	REAR BUMPER SENSOR @ \$300.00 (SN)	MISSING	600.00	200.00
	LESS 20% DISCOUNT		-120.00	-
			480.00	200.00
	<u>SPECIAL NETT ITEMS</u>			
2	TYRE @ \$250.00 (@ \$250.00 DISC 80%) (SN)	REAR PUNCTURE	500.00	200.00
1	TUBE REAR WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
			540.00	240.00
	<u>LABOUR</u>			
	TO PUTTY & SPRAY PAINT.		2,400.00	1,800.00
	TOWING.	* CHECK	100.00	-
	TO CHECK FRONT WIRING AND FOCUS HEAD LIGHT.		30.00	30.00
	TO REPLACE AIR CON CONDENSER & TOP UP GAS.	* CHECK	100.00	-
	TO REPLACE FRONT UNDER CARRIAGE.	* CHECK	300.00	-
	TO REPLACE REAR UNDER CARRIAGE.		280.00	240.00
	TO CHECK WHEEL ALIGNMENT.		80.00	80.00
	TO REMOVE & REFIX CUSHION SEAT & TRIMMING.		120.00	120.00

Report Ref No. CS/SMO20008156/Kvf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIX REAR WINDSCREEN GLASS.		120.00	120.00
	TO ANTI-RUST.		150.00	120.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT BUMPER LOWER SPOILER AND REAR BOOT LID.		2,400.00	2,000.00
			6,080.00	4,510.00
GRAND TOTAL			19,345.60	10,994.80
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$4,465.60 NETT)				10,994.80

Report Ref No. CS/SMO20008156/Kvf3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.