

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20008159/KQF3E2

**Date:** 08/09/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN17087719022
Claimant Vehicle No :	FX982T	Insured Vehicle No :	GBF6729L
Date of Loss:	13/01/2020	Nature of Claim:	TP
		Claim No:	SNM20D200359/C02/LEWLC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FX982T	Engine No:	NF125MDE5001900
Make & Model:	HONDA NF125MD, 125cc	Chassis No:	NF125MD5001900
Reg. Date:	26/08/2003 (Man. Year: 2003)	Odometer:	0 km
Colour:	Red/White		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	70/90 R17	Rear Tyre Size:	80/90 R17
Front Left Side:	Maxxis 4 mm	Rear Left Side:	Maxxis 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,648.71	3,758.71	2,890.00	43.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,470.00	480.00	990.00	67.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,118.71</b>	<b>4,238.71</b>	<b>3,880.00</b>	<b>47.79</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,118.71</b>	<b>3,000.00</b>	<b>5,118.71</b>	<b>63.05</b>

### INSPECTION

Date of Assignment:	25/08/2020	
Date Inspected:	14/08/2020 Inspected At:	Serve You Motor Service (HQ) BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-265 Singapore 569536
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 07 Sep 2020)	
<b>Parts:</b>	N/A	HONDA NF125MD 125cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FX982T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Distorted / Cut	230.00 FL	*230.00 FL
2	1		*BRACKET COMP FRONT FENDER	Repair	88.00 FL	*- FL
3	1		*FRONT WHEEL AXLE	Bent	106.90 FL	*106.90 FL
4	1		*FRONT RH FORK ASSY	Serviceable	495.00 FL	*- FL
5	1		*FRONT LH FORK ASSY	Serviceable	495.00 FL	*- FL
6	1		*FRONT RH DISC ROTOR	Warped	230.00 FL	*230.00 FL
7	1		*FRONT FORK STEERING STEM WITH BEARING	Bent / Jammed	450.00 FL	*450.00 FL
8	1		*FRONT COVER ASSY RH	Cracked	380.20 FL	*380.20 FL
9	1		*STAY FRONT COVER	Cracked	450.00 FL	*450.00 FL
10	1		*HEAD LAMP ASSY - CENTER	Cut	440.00 FL	*440.00 FL
11	1		*LEFT SWITCH ASSY	Serviceable	128.40 FL	*- FL
12	1		*RIGHT SWITCH ASSY	Cracked	145.00 FL	*145.00 FL
13	1		*CENTER BOX COVER	Cracked	188.60 FL	*188.60 FL
14	1		*LH FAIRING COVER	Serviceable	55.00 FL	*- FL
15	1		*RH FAIRING COVER	Distorted	55.00 FL	*55.00 FL
16	1		*STEERING HANDLE BAR	Distorted	195.00 FL	*195.00 FL
17	1		*BALANCER	O/S Dented	90.80 FL	*45.40 FL
18	1		*LH VIEW MIRROR	Missing	145.00 FL	*145.00 FL
19	1		*SIDE STAND	Distorted	105.00 FL	*105.00 FL
20	1		*MAIN STAND	Repair	335.00 FL	*- FL
21	1		*COVER SET CENTRAL BODY	Serviceable	590.00 FL	*- FL
22	1		*LH HANDLE COVER	Serviceable	175.20 FL	*- FL
23	1		*HEADLAMP SUPPORT BRACKET	Repair	45.00 FL	*- FL
24	1		*RH VIEW MIRROR	Missing	75.80 FL	*75.80 FL
25	1		*METER COVER ASSY	Serviceable	220.00 FL	*- FL
26	1		*HELMUT (\$88.00) (50%)	Cracked	79.20 FS	*44.00 FS
27	1		*ERP WITH BRACKET	Missing	220.00 FL	*220.00 FL
28	1		*FRONT CENTRAL BASKET	Mtg Cracked	110.00 FL	*110.00 FL
29	1		*REAR BOX BRACKET	Repair	120.00 FS	*- FS
30	1		*REAR BOX	Dented / Cut	280.00 FS	*280.00 FS
31	1		*FRONT NUMBER PLATE	Serviceable	30.00 FS	*- FS
32	1		*FRONT SPORT RIM	Repair	220.00 FS	*- FS
33	1		*FRONT TYRE	Serviceable	80.00 FS	*- FS
34	1		*STEERING CONE BEARING	Necessary	100.00 FS	*100.00 FS
35	1		*WHEEL BEARING	Necessary	120.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (S\$)**      **7,273.10**      **4,115.90**  
**- List Item Discount on L Items 10.00/10.00% (S\$)**      624.39      357.19

**Total Parts (S\$)**      **6,648.71**      **3,758.71**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REPLACE AND REALIGN ALL DAMAGED PORTIONS	New	450.00	180.00
2	TO REPLACE AND BALANCE FRONT RIM	New	150.00	20.00
3	TO KNOCK AND STRAIGHTEN CHASSIS BODY	New	280.00	0.00
4	TO REMOVE AND REFIT FRONT FORK ASSY	New	180.00	80.00
5	TO SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS ON DAMAGED PORTION	New	330.00	200.00
6	TO RESET AND ERASE FAULT CODE	New	80.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,470.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >