



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2007057
INV Date 19/10/2020
Reference CC4/FCI20008160/Eda3s2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SLU 5698B
Insured Veh. SH 7067U
Claim No. D20003034MFSH
Policy No. D-20094922MFSH
Accident Date 30/07/2020
Inspection Date 05/08/2020

Description	Total
Third Party Express Settlement	600.00
Subtotal	600.00
GST (7%)	42.00
Grand Total	642.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20008160/Eda3s2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-10-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7067U	Veh. Inspected	SLU 5698B
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20003034MFSH	Excess (\$)	0.00
Assign From	HENG DING CHAO	Assign Date	05/08/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA AXIO	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NKE1657144001	Colour	BLACK
Odometer	148491	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	SUNWIDE	5 mm
L/H Front Tyre	185/60 R15	SUNWIDE	5 mm
R/H Rear Tyre	185/60 R15	SUNWIDE	5 mm
L/H Rear Tyre	185/60 R15	SUNWIDE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/07/2020	Inspection Date	05/08/2020
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 5698B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	TO REPAIR SEE LABOUR	558.20	-
2	BONNET HINGES @ \$112.00	BENT	224.00	120.00
1	BONNET LOCK	BENT	289.00	90.00
1	FRONT BUMPER	BROKEN	498.20	498.20
1	FRONT BUMPER REINFORCEMENT	BENT	312.00	312.00
1	FRONT BUMPER SPONGE	BROKEN	198.00	120.00
2	FRONT BUMPER SIDE RETAINER @ \$45.00	BROKEN	90.00	90.00
1	FRONT BUMPER LOWER GRILLE	CUT	212.00	212.00
1	FRONT BUMPER GRILLE	NOT NECESSARY	321.00	-
2	FRONT BUMPER FOGLAMP COVER @ \$62.00	BROKEN 1PC ONLY	124.00	62.00
1	FRONT BUMPER UNDERCOVER TOP GARNISH	CRUSHED	159.00	159.00
1	FRONT BUMPER UNDER COVER	CRUSHED	287.00	287.00
2	FRONT BUMPER LOWER AIR ARCH @ \$84.00	CRUSHED 1PC ONLY	168.00	84.00
1	FRONT GRILLE (BASE)	BROKEN	590.30	590.30
1	FRONT GRILLE LOGO	NECESSARY	68.00	68.00
1	FRONT GRILLE CHROME	NOT NECESSARY	221.00	-
1	FRONT SUPPORT PANEL	DENTED	928.30	928.30
1	FRONT SUPPORT PANEL TOP GARNISH	CRUSHED	159.00	159.00
2	HEADLAMP @ \$760.50	BROKEN	1,521.00	1,521.00
2	HEADLAMP TOP PANEL @ \$162.00	BENT	324.00	324.00
1	AIR CLEANER HOUSING	BROKEN	258.00	258.00
1	AIR DUCT	NOT NECESSARY	102.00	-
1	WIPER WASHER TANK C/W MOTOR	BROKEN	321.00	321.00
1	WIPER GARNISH	BROKEN	519.60	519.60
1	WIPER SIDE GARNISH RH	NOT NECESSARY	48.00	-
1	FUSE BOX	BROKEN	350.40	350.40
1	FRONT WIRE HARNESS	BROKEN	321.00	321.00
1	SET ENGINE MOUNTING	NOT NECESSARY	1,211.00	-
1	AIRCOND CONDENSER	BENT	1,189.20	1,189.20

Report Ref No. CC4/FCI20008160/Eda3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	AIRCOND CONDENSER ARCH GARNISH @ \$48.00	NOT NECESSARY	96.00	-
1	AIRCOND SUCTION PIPE	BROKEN	325.00	325.00
1	AIRCOND DISCHARGE PIPE	NOT NECESSARY	311.00	-
1	RADIATOR	BENT	1,128.00	1,128.00
2	RADIATOR SUPPORT BRACKET @ \$42.00	BROKEN	84.00	84.00
1	FRONT FENDER RH	DENTED	465.20	465.20
2	FRONT FENDER COWLING @ \$225.60	CRUSHED 1PC ONLY	451.20	162.00
1	FRONT FENDER INNER PANEL RH	BENT	211.00	211.00
1	FRONT WHEEL HOUSING RH	BENT	680.60	680.60
1	FRONT FENDER EMBLEM "HYBRID" RH	NECESSARY	58.00	58.00
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	897.00	-
1	FRONT DOOR WEATHERSTIP RH	NOT NECESSARY	187.00	-
1	ROCKER PANEL RH	TO REPAIR SEE LABOUR	698.00	-
2	FRONT CHASSIS EXTENSION @ \$314.00	TO REPAIR SEE LABOUR	628.00	-
1	FRONT SHOCK ABSORBER RH	BENT	412.00	412.00
1	FRONT LOWER ARM RH	BENT	430.70	430.70
1	FRONT KNUCKLE ARM RH	BENT	521.00	450.00
1	FRONT KNUCKLE ARM BEARING RH	NECESSARY	125.00	125.00
1	FRONT DRIVESHAFT RH	BENT	1,125.00	1,125.00
1	FRONT CROSSMEMBER	BENT	1,325.60	1,325.60
1	FRONT LINKAGE	NOT NECESSARY	139.50	-
1	STEERING RACK AND PINION	NOT NECESSARY	1,987.00	-
1	STEERING ANGLE SENSOR (ADDITIONAL)	SHORTED	259.00	259.00
	LESS 25% DISCOUNT		-6,029.25	-3,956.27
			18,087.75	11,868.83
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	FRONT NUMBER PLATE GARNISH (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	SET FRONT BUMPER LOWER COVER CLIPS (SN)	NECESSARY	50.00	20.00

Report Ref No. CC4/FCI20008160/Eda3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIP (SN)	NECESSARY	50.00	20.00
1	FRONT FENDER SEALANT (SN)	NECESSARY	50.00	20.00
1	FRONT WHEEL RIM RH (SN)	CUT	800.00	400.00
1	FRONT TYRE RH (SN)	NOT NECESSARY	250.00	-
1	MISCELLANEOUS (SN)	NOT NECESSARY	200.00	-
			1,580.00	490.00
	LABOUR			
	TO CHECK ELECTRICAL WIRING.		80.00	30.00
	REMOVE AND RENEW UNDERCARRIAGE.		600.00	200.00
	TOWING FEE.		120.00	60.00
	AIR CON CONDENSER TOP UP AND VACUUM.		120.00	120.00
	REPAIR AND STRAIGHTEN CHASSIS FRAME.		600.00	400.00
	CHECK AND RESET FAULT CODE LIGHT ON.		150.00	100.00
	REMOVE AND REFIT RADIATOR AND CONDENSER.		120.00	50.00
	REMOVE AND REFIT ENGINE TO FACILITATE REPAIR.	NOT NECESSARY	450.00	-
	RESET HYBRID SYSTEM PROGRAMMING ECU. INCLUSIVE OF THE REPAIR OF, BONNET, FRONT DOOR RH, ROCKER PANEL RH AND FRONT CHASSIS EXTENSION.		2,800.00	300.00
	CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	APPLY ANTI RUST ON AFFECTED AREAS.		120.00	30.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,800.00	1,300.00
	PANEL BEATING ON AFFECTED AREAS.		1,800.00	1,300.00
	REMOVE AND RENEW STEERING ANGLE SENSOR. (ADDITIONAL)		60.00	60.00
			8,940.00	4,010.00
GRAND TOTAL			28,607.75	16,368.83
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,100.00

Report Ref No. CC4/FCI20008160/Eda3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 5698B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 5698B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 5698B

RE-INSPECTION

