

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008167/GEA3Q2

Date: 10/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100454338

Claimant
Vehicle No : SCL1952Y **Insured Vehicle No :** SGL129S

Date of Loss: 03/08/2020 Nature of Claim: TP Claim No: 3997453377SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCL1952Y	Engine No:	9HPGRB123827
Make & Model:	JAGUAR XJ6, 3.2 LWB (A)	Chassis No:	SAJJFAMG3BJ770878
Reg. Date:	01/03/1996 (Man. Year: 1996)	Odometer:	158069 km
Colour:	Red		
Engine Capacity:	3239 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R16	Rear Tyre Size:	225/60 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,744.00	4,521.60	8,222.40	64.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,100.00	1,840.00	62.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,684.00	5,621.60	10,062.40	64.16
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	15,684.00	4,500.00	11,184.00	71.31
+ GST 7.00/7.00% (S\$)	1,097.88	315.00	782.88	71.31
Nett Amount (S\$)	16,781.88	4,815.00	11,966.88	71.31
+ Loss of Use (8.0 x S\$130.00/day) (S\$)		1,040.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		140.00		
Nett Liability (S\$)		6,002.45		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment: 06/08/2020

Date Inspected: 06/08/2020 Inspected At:

Motor Edgevantage Pte Ltd (HQ)
160 Sin Ming Drive, Sin Ming AutoCity
#03-01/02
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*JAGUAR FRONT BUMPER COVER	Cracked	1,800.00 F	*1,200.00 FL
2	1		*JAGUAR FRONT BUMPER CHROME MOULDING LH	Cut	900.00 F	*200.00 FL
3	1		*JAGUAR FRONT BUMPER CHROME MOULDING RH	Broken	900.00 F	*200.00 FL
4	1		*JAGUAR FRONT BUMPER CHROME MOULDING CENTER	Broken	1,680.00 F	*300.00 FL
5	2		*JAGUAR BUMPER GUIDE BLOCK	Cracked	80.00 F	*40.00 FL
6	1		*JAGUAR FRONT BUMPER BEAM	Deformed	1,300.00 F	*900.00 FL
7	1		*JAGUAR FRONT BUMPER UNDERTRAY	Missing	600.00 F	*300.00 FL
8	1		*JAGUAR FRONT BUMPER SIDE MARKET LAMP RH (NO LIGHT)	Broken	88.00 F	*40.00 FL
9	1		*JAGUAR FRONT BUMPER SIDE MARKET LAMP LH (NO LIGHT)	Not Necessary	88.00 F	*- FL
10	1		*JAGUAR FRONT BUMPER FOG LAMP RH	Not Necessary	720.00 F	*- FL
11	1		*JAGUAR FRONT BUMPER FOG LAMP LH	Not Necessary	720.00 F	*- FL
12	1		*JAGUAR FRONT BUMPER INDICATE LAMP RH	Cracked	227.00 F	*110.00 FL
13	1		*JAGUAR FRONT BUMPER INDICATE LAMP LH	Not Necessary	227.00 F	*- FL
14	1		*JAGUAR FRONT HEADLAMP RH	Not Necessary	1,230.00 F	*- FL
15	1		*JAGUAR FRONT HEADLAMP LH	Cracked	1,230.00 F	*1,050.00 FL
16	1		*JAGUAR BRAKE COOLING DUCT RH	Missing	100.00 F	*50.00 FL
17	1		*JAGUAR BRAKE COOLING DUCT LH	Broken	100.00 F	*50.00 FL
18	1		*JAGUAR FRONT BUMPER NUMBER PLATE HOLDER (BLACK)	Cut	150.00 F	*70.00 FL
19	1		*JAGUAR FRONT RADIATOR GRILLE VANE	Deformed	540.00 F	*450.00 FL
20	1		*FRONT NUMBER PLATE	Scratched	40.00 F	*40.00 FL
21	2		*JAGUAR STRUT TO BEAM SPACER	Broken	24.00 F	*24.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 12,744.00 **5,024.00**
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 502.40

Total Parts (\$\$) 12,744.00 **4,521.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGES FROM PLAZA SINGAPURA TO WORKSHOP	New	140.00	0.00
2	TO REPLACE REPAIR ,FRONT BUMPER ,CHROME MOULDING FRONT BUMPER BEA, TRANSFER BUMPER PARTS ,BOTH FRONT HEADLAMP ,FOG LAMP ,BUMPER MARKER LAMP CHECK WIRING ,CONNECTOR ,ETC	New	1,600.00	500.00
3	TO PUTTY ,SPRAY PAINTING ,FRONT BONNET ,LH FRONT FENDER RH FRONT FENDER ,FRONT BUMPER COVER	New	1,200.00	600.00
Gross Labour Cost (\$\$)			2,940.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >