

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20008169/T1EA3Q2
Date: 23/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900161965
Claimant Vehicle No :	SH8772K	Insured Vehicle No :	SMP1762P
Date of Loss:	05/08/2020	Nature of Claim:	TP
		Claim No:	4073780686SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8772K		
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Engine No:	D4FDEU475257
Reg. Date:	07/05/2015 (Man. Year: 2015)	Chassis No:	KMHLB41UMFU068819
Colour:	Blue	Odometer:	812699 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,952.16	1,952.16	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	510.00	140.00	21.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,602.16	2,462.16	140.00	5.38
Approved Total (Overridden) (S\$)		1,950.00		

(S\$)	2,602.16	1,950.00	652.16	25.06
+ GST 7.00/7.00% (S\$)	182.15	136.50	45.65	25.06
Nett Amount (S\$)	2,784.31	2,086.50	697.81	25.06
+ Loss of Use (1.5 x S\$50.00/day) (S\$)		75.00		
+ Car Rental (S\$)		83.01		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		2,252.00		
Global Sum Settlement (S\$)		2,250.00		

INSPECTION

Date of Assignment: 06/08/2020

Date Inspected: 06/08/2020

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER W LIP & FOG LAMP C	Deformed	1,052.20 FL	*1,052.20 FL
2	1		*LAMP ASSY -HEAD LH	Cracked	1,388.00 FL	*1,388.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					2,440.20	2,440.20
- List Item Discount on L Items 20.00/20.00% (S\$)					488.04	488.04
Total Parts (S\$)					1,952.16	1,952.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	300.00	280.00
2	SPRAYPAINT CHARGE	New	300.00	200.00
3	CHECK ALL LIGHTING	New	50.00	30.00
Gross Labour Cost (\$\$)			650.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >