

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008170/KEA3Q2

Date: 02/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100454187

Claimant
Vehicle No : SFF25B **Insured Vehicle No :** SLA3051K

Date of Loss: 05/08/2020 Nature of Claim: TP Claim No: 3373518301SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFF25B		
Make & Model:	BMW 520I, 2.0 AT D/AB 2WD 4DR LED NAV (A)	Engine No:	A0160596N20B20B
Reg. Date:	31/03/2014 (Man. Year: 2013)	Chassis No:	WBA5A32010D334089
Colour:	Metallic Dark Blue	Odometer:	167853 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45ZR18	Rear Tyre Size:	245/45ZR18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,799.50	2,634.03	6,165.47	70.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,840.00	1,300.00	1,540.00	54.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,639.50	3,934.03	7,705.47	66.20
Approved Total (Overridden) (\$\$)		3,150.00		
Nett Amount (\$\$)	11,639.50	3,150.00	8,489.50	72.94
+ Loss of Use (5.0 x S\$120.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,757.45		

INSPECTION

Date of Assignment: 06/08/2020

Date Inspected: 11/08/2020 Inspected At: Otto Car Pte Ltd (HQ)
176 Sin Ming Drive, #02-16 Sin Ming
Autocare
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	2,625.00 F	*1,571.95 FL
2	1		*REAR BUMPER CLIPS	Necessary	45.00 F	*45.00 FL
3	1		*REAR BUMPER REFLECTOR	Serviceable	84.00 F	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	1,007.50 F	*691.75 FL
5	1		*REAR BUMPER RETAINER,UPPER	Distorted	775.00 F	*180.00 FL
6	1		*REAR BUMPER RETAINER,LOWER	Cracked	165.00 F	*165.00 FL
7	1		*REAR BUMPER RETAINER,SIDE	Serviceable	260.00 F	*- FL
8	1		*BOOTLID	Repair	2,835.00 F	*- FL
9	1		*BOOTLID WEATHERSTRIP	Serviceable	240.00 F	*- FL
10	1		*EMBLEM BMW LOGO	Necessary	125.00 F	*85.00 FL
11	1		*EMBLEM 520I	Necessary	98.00 F	*98.00 FL
12	1		*REAR BUMPER UNDER COVER	Cracked	90.00 F	*90.00 FL
13	1		*SET REVERSE SENSOR	Serviceable	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,799.50	2,926.70
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	292.67
Total Parts (\$)	8,799.50	2,634.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE/REFIT/RENEW/REPLACE AFFECTED PARTS	New	1,350.00	500.00
2	SPRAY PAINTING	New	900.00	600.00
3	CHECK WIRING HARNESS AND FUNCTION OF REVERSE SENSOR	New	80.00	20.00
4	REMOVE AND INSTALL REVERSE SENSOR	New	60.00	60.00
5	RESET FAULT CODE	New	450.00	120.00
Gross Labour Cost (\$\$)			2,840.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >