

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20008174/QGS3Q2

Date: 06/01/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SG1184J	Insured Vehicle No :	SHD6774U
Date of Loss: 04/08/2020	Nature of Claim: TP	Claim No: MCT20080046

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG1184J		
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 D (A)	Engine No:	902926C1101258
Reg. Date:	07/07/2016 (Man. Year: 2015)	Chassis No:	WEB62808323130019
Colour:	Multi-colour	Odometer:	377526 km
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,639.05	0.00	7,639.05	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,192.00	1,305.00	887.00	40.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,831.05	1,305.00	8,526.05	86.73
+ Loss of Use (6.0 x S\$250.00/day) (S\$)		1,500.00		
		Nett Liability (S\$)	2,805.00	

INSPECTION

Date of Assignment:	07/08/2020	
Date Inspected:	07/08/2020 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: OI SUN PIN

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Sep 2020)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG1184J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR RH, FOR MB CITARO O530	Repair	837.84 F	*- F
2	1		*FLAP , RADIATOR FOR MB CITARO O530	Repair	5,445.00 F	*- F
3	1		*LAMP TAIL, REAR LH FOR MB CITARO O530	Serviceable	1,261.71 F	*- F
4	1		*LAMP SIDE MARKER FOR MB CITARO O530 BUS	Serviceable	94.50 F	*- F

F=Franchise part.

Total Parts (\$\$) **7,639.05** **0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,590.00	795.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	602.00	510.00
			Gross Labour Cost (\$\$)	1,305.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >