

CL APPRAISER PTE LTD

24 Penshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Peh2rent Pte Ltd
C/o: The Mechanic (Private Limited)
25 Kaki Bukit Road 4
#05-85 Synergy@KB, Singapore 417800

Date : 13 March 2020
Our ref : TMPL/03/2003/TP

Accident Date : 05 March 2020
Inspection Date : 09 March 2020
Repairer Name : The Mechanic (Private Limited)
25 Kaki Bukit Road 4
#05-85 Synergy@KB, Singapore 417800

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SJX 7459 U
Make / Model : Honda Vezel
Chassis No : RU11105067
Engine No : L15B4025137

Year / Capacity : 2015 / 1496 cc
Colour : White
Mileage : 118894

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: CST	215/60 R16	5 mm	Sport
Front Offside	: CST	215/60 R16	5 mm	Sport
Rear Nearside	: Continental	215/60 R16	5 mm	Sport
Rear Offside	: Continental	215/60 R16	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 72 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 6,200.00** on a contractual basis.

Under normal circumstances, the repair period would be about 6 (Six) working days.



SCL APPRAISER PTE LTD

Vehicle Registration No: SJX 7459 U

Our Ref No: TMPL/03/2003/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear windscreen moulding	Necessary	\$ 121.80	\$ 121.80
1	Rear tailgate	Damage	\$ 1,287.60	\$ 1,287.60
2	Rear tailgate dampers	Intact	\$ 331.60	
1	Rear tailgate inner trim board	Damage	\$ 225.00	\$ 225.00
2	Rear tailgate lamps	Damage	\$ 570.00	\$ 570.00
1	Rear tailgate lock	Damage	\$ 269.50	\$ 269.50
1	Rear tailgate logo	Necessary	\$ 40.30	\$ 40.30
1	Rear tailgate rubber	Necessary	\$ 227.00	\$ 227.00
1	Rear tailgate "VEZEL" emblem	Necessary	\$ 56.20	\$ 56.20
2	Rear taillamps	Damage	\$ 1,390.00	\$ 1,390.00
1	Rear end panel	Repair	\$ 585.80	
1	Rear end panel inner garnish	Damage	\$ 160.50	\$ 160.50
1	Rear bumper	Damage	\$ 950.60	\$ 950.60
2	Rear bumpers - side	Damage	\$ 450.60	\$ 450.60
2	Rear bumper brackets	Damage	\$ 97.00	\$ 97.00
2	Rear bumper reflectors	Damage	\$ 303.80	\$ 303.80
2	Rear bumper side retainers	Necessary	\$ 101.80	\$ 101.80
			\$ 7,169.10	\$ 6,251.70
		<i>Less 20%</i>	<i>\$ 1,433.82</i>	<i>\$ 1,250.34</i>
	Total Cost - List Items		\$ 5,735.28	\$ 5,001.36

SPECIAL NETT ITEMS

1	Rear windscreen sealant	Necessary	\$ 80.00	\$ 50.00
1	Rear bumper clip (1 set)	Necessary	\$ 50.00	\$ 50.00
1	Rear reverse sensor (1 set)	Damage	\$ 450.00	\$ 450.00
	Total Cost - Special Nett items		\$ 580.00	\$ 550.00

Total cost of parts

\$ 6,315.28 \$ 5,551.36

Vehicle Registration No: SJX 7459 U

Our Ref No: TMPL/03/2003/TP

S/No	Description	Repairer's Estimate	Revised Amount
Total cost of parts c/f		\$ 6,315.28	\$ 5,551.36
 <u>LABOUR</u>			
1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00
3	To remove and refit rear reverse sensor.	\$ 120.00	\$ 80.00
4	To transfer rear tailgate mechanism and wiring assembly to assist repair.	\$ 80.00	\$ 80.00
5	To remove and refit rear windscreen glass.	\$ 180.00	\$ 120.00
6	To apply undercoating on repaired and replaced panel.	\$ 100.00	\$ 60.00
7	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,000.00	\$ 750.00
8	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,200.00	\$ 880.00
GRAND TOTAL		\$ 9,225.28	\$ 7,691.36

C L APPRAISER PTE LTD

Vehicle Registration No: SJX 7459 U

Our Ref No: TMPL/03/2003/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 6,200.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser