

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1 #05-18, Singapore 757700

Tel: 64688834 Fax: 64622278 E-mail: info@automotiverepaircentre.com.sg ESTIMATE NO.: EST2008-098

DATE: 8-Aug-2020 POLICY NO.: P10124736R01

VEHICLE REG. NO. : SKZ6102H

VEHICLE MAKE: BMW 116D-1.5 D 5DR HATCH

TO Motor Claim Department

AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

190 Clemenceau Avenue #03-01,

Singapore Shopping Centre, Singapore 239924

Tel: 6221 2199 Fax: 67250853

| FOR SURVEYOR |
|--------------|
|--------------|

ESTIMATE REPAIR COST

| NO. | SPARE PARTS | QUANTITY | a d i U | NIT COST | то | TAL COST |
|---|---|---|----------|----------------|---------|-----------|
| 1 | | | | | | 2500 FLL. |
| - | Acoustic (Engine) Cover | 1 | \$ | 169.49 | \$ | 169.49 |
| 2 | Intake Manifold with Flap Control / 15 M | 1 | \$ | 1,151.15 | \$ | 1,151.15 |
| 3 | Basic DDE Control Unit | 1 | \$ | 2,399.99 | S | 2,399,99 |
| 4 | Wiring Harness Engine Glow Module | 1 | 5 | 153.70 | S | 153.70 |
| 5 | Wiring Harness Engine Injector Module / BN | 1 | s | 537.86 | s | 537.86 |
| 6 | Wiring Harness Engine Gearbox Module / DN | 1 | s | 537.86 | \$ | 537.86 |
| 7 | Mechanical Belt Tensioner | 1 | s | 172,75 | s | 172.75 |
| 8 | Ribbed V-Belt | 1 | \$ | 37.10 | S | 37.10 |
| 9 | Charging Alternator | 1 | s | 1,099.61 | \$ | 1,099.61 |
| 10 | A/C Compressor | 1 | 5 | 2,245.76 | 5 | 2,245.76 |
| 11 | Part Cost Plus 10% | | <u> </u> | 2,243.70 | 5 | 850.53 |
| | | | Tota | l Spare Parts | \$ | |
| | SPECIAL NETT | | 1000 | i spare raits | | 9,355.80 |
| | | | Tota | l Special Nett | \$ | • 1 |
| | LABOUR | Т - | 1 | | | |
| 12 | REMOVE, REFIT ENGINE TO FACILITATE REPAIR | 1 | s | 600.00 | \$ | 600.00 |
| 13 | REMOVE, REFIT ENGINE WIRING HARNESS | 1 | s | 600.00 | | |
| 14 | RESET, DIAGNOSTIC AND REPROGRAM BMW FAULT MEMORIES | 1 | \$ | | \$ | 600.0 |
| 15 | SPECIALIZED CHECK AND RECTIFY BMW ELECTRICAL WIRING | | \$ | 500.00 | \$ | 500.0 |
| stima | te prepared by: Raymond Tan | | | 300.00 | \$ | 300.0 |
| The above is an estimate based on our inspection and does not cover any | | | | \$ | 2,000.0 | |
| additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on | | | | | \$ | 11,355.8 |
| the first in a damaged parts are discovered which may not be evident on | | | | Add CCT o TO | | |

the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Add GST @ 7% 794.91 Total Amount Payable 12,150.70

Sun Pin (Ltt)

Day -?

Repair dy-5 dys. 1971 bothe pun phote

LKK Auto Consultants Hence notify

- the Repairer of the following:
- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: