

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG20005185/R1TF3E2-1
Date: 27/08/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: A28795104MCX
Claimant Vehicle No : SMQ4130M	Insured Vehicle No : SMQ2808E
Date of Loss: 11/04/2020	Nature of Claim: TP Claim No: 623171

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ4130M		
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 (A)	Engine No:	CAV135113
Reg. Date:	16/12/2009 (Man. Year: 2009)	Chassis No:	WVWZZZ13ZAV419591
Colour:	Grey	Odometer:	115598 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40Z R18	Rear Tyre Size:	235/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,490.30	9,078.50	6,411.80	41.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,230.00	1,910.00	2,320.00	54.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,720.30	10,988.50	8,731.80	44.28
Approved Total (Overridden) (S\$)		8,800.00		
Nett Amount (S\$)	19,720.30	8,800.00	10,920.30	55.38

INSPECTION

Date of Assignment:	14/04/2020	
Date Inspected:	15/04/2020 Inspected At:	Kj Car Repair (HQ) 1 Soon Lee Street #06-40 Pioneer Centre Singapore 627605
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Aug 2020)
Parts:	M1-COUPE	VOLKSWAGEN SCIROCCO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ4130M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Damaged	1,025.00 FL	*1,025.00 FL
2	1		*FRONT N/S HEADLAMP	Damaged	952.00 FL	*850.00 FL
3	1		*FRONT N/S HEADLAMP TOP PANEL	Serviceable	92.00 FL	*- FL
4	1		*FRONT BUMPER	Damaged	1,088.00 FL	*1,088.00 FL
5	1		*FRONT BUMPER FOG LAMP COVERING	Repair	175.00 FL	*- FL
6	1		*FRONT BUMPER INNER SPONGE	Intact	210.00 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Intact	554.00 FL	*- FL
8	2		*FRONT BUMPER SIDE RETAINERS	Necessary	70.00 FL	*70.00 FL
9	1		*FRONT N/S FENDER	Damaged	670.00 FL	*570.00 FL
10	2		*FRONT N/S FENDER INNER SHIELDS	Damaged	378.00 FL	*285.00 FL
11	2		*FRONT WHEEL HUB WITH BEARINGS	Damaged	1,040.00 FL	*770.00 FL
12	2		*FRONT SHOCK ABSORBERS	Damaged	900.00 FL	*772.00 FL
13	2		*FRONT KNUCKLE ARMS	Damaged	1,250.00 FL	*916.00 FL
14	2		*FRONT LOWER ARMS	Damaged	724.00 FL	*724.00 FL
15	1		*FRONT N/S DRIVE SHAFT	Damaged	1,640.00 FL	*1,100.00 FL
16	1		*FRONT N/S TIE ROD	Damaged	145.00 FL	*145.00 FL
17	1		*FRONT N/S DOOR	Repair	2,057.00 FL	*- FL
18	1		*FRONT N/S DOOR RUBBER	Not Necessary	528.00 FL	*- FL
19	1		*FRONT N/S DOOR SIDE MIRROR	Damaged	869.00 FL	*600.00 FL
20	1		*SET FRONT BUMPER CLIP	Necessary	60.00 FS	*40.00 FS
21	2		*FRONT TYRE	Damaged	900.00 FS	*315.00 FS
22	2		*FRONT WHEEL RIMS	Damaged	1,600.00 FS	*700.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,927.00	9,970.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,436.70	891.50
Total Parts (S\$)	15,490.30	9,078.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING, LIGHTING AND RESETTING HEADLAMPS FOCUSSING	New	80.00	30.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	600.00	240.00
3	TO CONDUCT WHEEL ALIGNMENT	New	180.00	80.00
4	TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR	New	150.00	0.00
5	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
6	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,600.00	700.00
7	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,500.00	800.00
Gross Labour Cost (S\$)			4,230.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >