

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20008181/T1RS3Q2**Date:** 17/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993949
Claimant Vehicle No :	SHD3027M	Insured Vehicle No :	YP6520X
Date of Loss:	06/08/2020	Nature of Claim:	TP
		Claim No:	9304189330SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3027M		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4DFDU606561
Reg. Date:	07/04/2016 (Man. Year: 2015)	Chassis No:	KMHLB41UMGU086948
Colour:	Blue	Odometer:	520366 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,931.88	2,878.24	1,053.64	26.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,390.00	1,115.00	275.00	19.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,321.88	3,993.24	1,328.64	24.97
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	5,321.88	3,200.00	2,121.88	39.87
+ GST 7.00/7.00% (S\$)	372.53	224.00	148.53	39.87
Nett Amount (S\$)	5,694.41	3,424.00	2,270.41	39.87
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Car Rental (6.0 x S\$57.48/day) (S\$)		344.88		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		4,076.37		

INSPECTION

Date of Assignment:	07/08/2020	
Date Inspected:	07/08/2020	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	2,174.90 FL	*2,174.90 FL
2	1		*BOOT HINGE /RH	Repair	142.30 FL	*- FL
3	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
4	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
5	1		*BOOT LID I 40	Necessary	27.90 FL	*27.90 FL
6	1		*BOOT LID LAMP /RH	Cracked	565.60 FL	*565.60 FL
7	1		*TAIL LAMP /RH	Cracked	697.80 FL	*697.80 FL
8	1		*REAR BUMPER	Repair	1,106.00 FL	*- FL
9	1		*REAR NUMBER PLATE	Not Necessary	55.00 FS	*- FS
10	1		*BOOTLID COMFORT LOGO STICKER	Necessary	30.00 FS	*30.00 FS
11	1		*BOOTLID COMFORT TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
					Sub Total (\$\$)	4,886.10 3,582.80
					- List Item Discount on L Items 20.00/20.00% (\$\$)	954.22 704.56
					Total Parts (\$\$)	3,931.88 2,878.24

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	540.00	420.00
2	SPRAY PAINTING CHARGE	New	640.00	600.00
3	TOWING FEE	New	60.00	35.00
4	TUFF KOTE	New	90.00	30.00
5	CHECK LIGHTING	New	60.00	30.00
Gross Labour Cost (\$)			1,390.00	1,115.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >