



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 1486G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	CRUMPLED	1,843.00	1,450.00
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	985.00	-
1	FRONT BUMPER ENERGY ABSORBER	SERVICEABLE	315.00	-
2	FRONT BUMPER SIDE RETAINER L/R @\$68.00	O/S BROKEN	136.00	68.00
1	FRONT BUMPER SIDE BRACKET RH	CRACKED	115.00	115.00
1	FRONT BUMPER SIDE GRILLE RH	SERVICEABLE	79.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	54.00	54.00
1	FRONT BUMPER LOWER COVER RH	SERVICEABLE	68.00	-
1	FRONT FOG LAMP RH	SERVICEABLE	197.00	-
1	FRONT HEADLAMP WASHER COVER RH	SERVICEABLE	56.00	-
1	FRONT HEADLAMP WASHER ASSY RH	SERVICEABLE	197.50	-
1	FRONT HEADLAMP ASSY RH	SCRATCHED	2,611.00	2,611.00
1	FRONT BUMPER CORNER SENSOR RH	SCRATCHED	308.00	308.00
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	1,395.00	-
1	FRONT FENDER INNER LINDER RH	SERVICEABLE	197.00	-
	LESS 10% DISCOUNT		-	-460.60
			8,556.50	4,145.40
<u>LABOUR</u>				
	SPRAY PAINTING ON ABOVE NEW & REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS.		800.00	400.00
	REMOVE DAMAGED PARTS,KNOCK OUT DENT,STRAIGHTEN,PANEL BEATING,REMOVE & REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS,RESHAPE,REFIT,ADJUST,REPLACE AND REALIGN ALL RELEVANT PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		900.00	300.00
	TO CARRY OUT DIAGNOSTIC CHECKS AND RESET.		380.00	50.00
	TO CAVITY PRESERVATION ON ALL AFFECTED AREAS.		100.00	30.00
	CHECK WIRING,LIGHTING,ELECTRICAL CIRCUIT,RECONNECTION WIRE,SOCKET,FOCUS HEADLIGHTS & CENTRE LOCKING SYSTEM FOR PROPER FUNCTION.		50.00	30.00

Report Ref No. CS3/LPC20005089/Qqf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REINSTALL FRONT BUMPER SENSOR.		120.00	30.00
			2,350.00	840.00
GRAND TOTAL			10,906.50	4,985.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS3/LPC20005089/Qqf3e2-1

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.