

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20008193/UDA3Q2

**Date:** 27/08/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800066049

**Claimant**  
**Vehicle No :** SLN7811P **Insured Vehicle No :** SKT3760J

Date of Loss: 07/08/2020 Nature of Claim: TP Claim No: 2927104307SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLN7811P</b>		
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Engine No:	PE20893808
Reg. Date:	17/05/2017 (Man. Year: 2017)	Chassis No:	JM6GL1071H0118523
Colour:	White	Odometer:	38942 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,269.44	1,786.88	1,482.56	45.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,130.00	1,320.00	53.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>5,719.44</b>	<b>2,916.88</b>	<b>2,802.56</b>	<b>49.00</b>
<b>+ Car Rental (6.0 x S\$100.00/day) (\$\$)</b>		600.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>3,518.88</b>		

### INSPECTION

Date of Assignment: 07/08/2020

Date Inspected: 07/08/2020 Inspected At: Hup Motor Trading & Service (HQ)  
Blk 9004 Tampines Street 93, #01-120  
Singapore 528838

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	1,266.60 FL	*1,266.60 FL
2	20		*REAR BUMPER CLIPS (TOP & LOW)	Necessary	80.00 FL	*80.00 FL
3	2		*REAR BUMPER O/S & N/S TOW BAR COVER	Not Necessary	69.80 FL	*- FL
4	2		*REAR BUMPER O/S & N/S REFLECTOR	Not Necessary	106.00 FL	*- FL
5	1		*SET REAR BUMPER O/S & N/S INNER REVERSE SENSOR	Shorted/Cracked	361.80 FL	*361.80 FL
6	1		*SET REAR BUMPER O/S & N/S OUTER REVERSE SENSOR	Shorted/Cracked	407.20 FL	*407.20 FL
7	2		*REAR BUMPER O/S & N/S TOP RETAINER	Not Necessary	70.00 FL	*- FL
8	2		*REAR BUMPER O/S & N/S SIDE RETAINER	Cracked	88.00 FL	*88.00 FL
9	4		*REAR BUMPER O/S & N/S SIDE BRACKET CLIPS	Necessary	30.00 FL	*30.00 FL
10	1		*REAR BUMPER REINFORCEMENT	Repair	538.30 FL	*- FL
11	2		*REAR BUMPER REINFORCEMENT O/S & N/S BRACKET	Not Necessary	170.60 FL	*- FL
12	1		*BOOT LID MAZDA 6 EMBLEM	Not Necessary	67.80 FL	*- FL
13	1		*BOOT LID SKYACTIVE EMBLEM	Not Necessary	74.70 FL	*- FL
14	1		*REAR END PANEL	Repair	606.70 FL	*- FL
15	1		*REAR END PANEL TOP GARNISH	Not Necessary	122.30 FL	*- FL
16	6		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	27.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,086.80</b>	<b>2,233.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	817.36	446.72

<b>Total Parts (\$\$)</b>	<b>3,269.44</b>	<b>1,786.88</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	20.00
2	TO REMOVE & REFIX REAR CARPET,FLOOR MAT,GARNISH,TOOL SET SPONGE,FLOOR BOARD COVER & NECESSARY PARTS,TO ENABLE REPAIR REAR END PANEL & NECESSARY PARTS	New	120.00	60.00
3	TO DIAGNOSE & RESET REAR REVERSE SENSOR	New	120.00	50.00
4	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	60.00	0.00
5	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS,TO JACK,STRAIGHTEN & KNOCKING OUT REAR END PANEL,BOOT LID & NECESSARY PARTS,TO WELD,RENEW & ALIGN ABOVE PARTS	New	850.00	400.00
6	TO PUTTY & RESPRAY PAINTING (PEARL COLOUR) ON ALL AFFECTED ACCIDENT PARTS	New	1,250.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,450.00</b>	<b>1,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >