



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 8154P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HEADLAMP RH-HID	HDR CRACKED	1,917.60	1,917.60
1	HEADLAMP CONTROL UNIT RH	SERVICEABLE	980.00	-
1	HEADLAMP LOWER BRACKET RH	SERVICEABLE	250.00	-
1	HEADLAMP NOZZLE COVER RH	SERVICEABLE	215.00	-
1	HEADLAMP NOZZLE LAMP RH	SERVICEABLE	399.00	-
1	FRONT GRILLE C/W CHROME RH	CRACKED	420.00	420.00
1	FRONT BUMPER	DEFORMED	1,839.60	1,244.00
2	FRONT BUMPER SIDE RETAINER @\$180.00	BENT	360.00	240.00
1	FRONT BUMPER BRACKET RH	SERVICEABLE	237.60	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	948.00	-
1	FRONT BUMPER SPONGE	SERVICEABLE	510.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	450.00	-
1	REAR BUMPER	TORN	1,907.35	1,043.00
1	REAR BUMPER REINFORCEMENT	DENTED	697.00	566.00
1	REAR BUMPER INNER LOWER GARNISH	CRACKED	425.00	284.00
2	REAR BUMPER REVERSE SENSOR	MALFUNCTION	464.00	450.00
1	REAR LAMP RH	CRACKED	1,848.00	528.00
1	REAR LAMP SIDE GARNISH RH	SERVICEABLE	320.50	-
	LESS 5% DISCOUNT		-709.43	-334.63
			13,479.22	6,357.97
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER EMBLEM (SN)	NECESSARY	101.80	101.80
1	FRONT NUMBER PLATE (SN)	DENTED	60.00	40.00
10	FRONT BUMPER CLIP (SN)	NECESSARY	80.00	30.00
10	REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
2	TAIL LAMP CLIP (SN)	NECESSARY	40.00	30.00
			361.80	231.80
<u>LABOUR</u>				
	TO CHECK WIRING SYSTEM (FRONT & REAR).		250.00	100.00
	REMOVE & REFIT REAR BUMPER SENSOR.		200.00	30.00

Report Ref No. CS3/FWD20005214/Eyf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	STRAIGHTEN END PANEL,REAR FENDER & REPLACE DAMAGE PARTS.	NOT NECESSARY	1,500.00	700.00
	SPRAY PAINTING CHARGES.		1,200.00	1,000.00
	CONDUCT STANDARD POST REPAIR DIAGNOSTIC SCAN.		800.00	-
			3,950.00	1,830.00
GRAND TOTAL			17,791.02	8,419.77

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,750.00
---	--	--	--	----------

Report Ref No. CS3/FWD20005214/Eyf3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.