BLOCK 607 ELIAS ROAD # 05-192 SINGAPORE (510607) BUSINESS REGN. No. 53193457L Hp 96699986

#### **INVOICE**

Mr.

Jason Xie Zhi Hao

21 Swiss View

Singapore 288027

Invoice No

: PA/20070014/tpw

Our Ref

: PA/SKH8154/0420/tpw

Date

: 17 July 2020

Claim Type	Third Party D	ate of Accident	: 06 April 2020
Vehicle No.	SKH 8154 P	ate of Inspection	: 17 April 2020
No	Description		Amount (S\$)
1	Survey fees inclusive of		\$725.00
	Transportation and		
	Photographs (50) copies		
	T Holographs (50) copies		

Singapore Dollar: Seven Hundred And Twenty-Five Only

All payments made payable to : Prudent Adjustors Services

Prudent Adjustors Services

Bok Jee Tan

BLOCK 607 ELIAS ROAD # 05-192 SINGAPORE (510607) BUSINESS REGN. No. 53193457L Hp 96699986

#### VEHICLE DAMAGE INSPECTION REPORT

Mr.

Jason Xie Zhi Hao

21 Swiss View

Singapore 288027

Our Ref

: PA/SKH8154/0420/tpw

Date

: 17 July 2020

REFERENCES

Claim Type

: Third Party

Date of Accident

: 06 April 2020

Vehicle No.

: SKH 8154 P

Date of Assignment

: 16 April 2020

Make

: BMW

Date of Inspection

: 17 April 2020

Model

: 3161 1.6 AT D/AB 4DR ABSHID

Date of Re-inspection

: 21 April 2020

Reg. Date

: 18 January 2018

COE Expiry

: 17 January 2023

Color

: Red

Chassis No

: WBA3A12050J719524

Odometer

: 121,608 km

Engine No

: Blocked

TYRE CONDITION

Make

Front near side Pirelli

Front off side Pirelli

Rear near side Pirelli

Rear off side Pirelli

Size

225/50-17

225/50-17

225/50-17

225/50-17

Thread Balance

5 mm

5 mm

6 mm

6 mm

### GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at front and rear portion.

Please refer to photographs and assessment of repairs for details

Enclosed (50) photographs depicting damages.

### INSPECTION AND ASSESSMENT SUMMARY

**Original Quotation** 

: \$17,791.02

Revised Assessment

\$13,150.00 Lump sum

Survey conducted at JD Motorsports Pte Ltd

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately Seven (7) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

Vehicle No: SKH 8154 P

## ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

Headlamp RH - HID			7		Original	Revised	
2 Headlamp control unit RH       1 pc       Necessary       980.00 SVC       980.00 SVC       980.00 SVC       250.00 SVC       260.00 SVC       260	S/N	Description Material	Qty	Condition	Quotation	Quotation	Į.
Headlamp lower bracket RH 1 pc	1	Headlamp RH - HID	1 pc	Hdr cracked	1,917.60	1,917.60	$\checkmark$
Headlamp lower bracket RH 1 pc	2	Headlamp control unit RH	1 pc	Necessary	980.00	SVC 980.00	X
Headlamp nozzle pump RH 1 pc Serviceable 399.00 ~ Front grille c/w chrome RH 1 pc Cracked 420.00 420.00 √ Front bumper 1 pc Deformed 1,839.60 1244 √1,839.60 7 Front bumper side retainer @ \$180/- 2 pcs Bent 1 pc - \$120 360.00 240 √ 360.00 7 Front bumper bracket RH 1 pc Bent 237.60 svc 237.60 > Front bumper reinforcement 1 pc Dented 948.00 svc 948.00 > Front bumper sponge 1 pc Cracked 510.00 svc 510.00 > Front bumper lower grille 1 pc Cracked 450.00 svc 450.00 > Rear bumper 1 pc Tom 1,907.35 1043 √1,907.35 1043	3	Headlamp lower bracket RH	1 pc	Bent		0.00	×
Front grille c/w chrome RH 1 pc Cracked 420.00 420.00 v Front bumper 1 pc Deformed 1,839.60 1244 v 1,839.60 Front bumper side retainer @ \$180/- 2 pcs Bent 1 pc - \$120 360.00 240 v 360.00 Front bumper bracket RH 1 pc Bent 237.60 svc 237.60 pront bumper reinforcement 1 pc Dented 948.00 svc 948.00 pront bumper sponge 1 pc Cracked 510.00 svc 510.00 pront bumper lower grille 1 pc Cracked 450.00 svc 450.00 pront bumper lower grille 1 pc Tom 1,907.35 1043 v 1,907.35 pront bumper reinforcement 1 pc Dented 697.00 566 v 697.00 pront bumper inner lower garnish 1 pc Cracked 425.00 284 v 425.00 pront bumper reverse sensor @ \$462/-4 pcs- Malfunction 1 pc - \$225464.00 450 v 464.00 pront sear lamp RH 1 pc Cracked 1,848.00 528 v 1,848.00 pront sear lamp side garnish RH 1 pc Cracked 1,848.00 528 v 1,848.00 pront sear lamp side garnish RH 1 pc Cracked 1,848.00 528 v 1,848.00 pront sear lamp side garnish RH 1 pc Cracked 1,848.00 528 v 1,848.00 pront sear lamp side garnish RH 1 pc Cracked 1,848.00 528 v 1,848.00 pront sear lamp side garnish RH 1 pc Cracked 1,848.00 528 v 1,848.00 pront search sear lamp side garnish RH 1 pc Cracked 1,848.00 528 v 1,848.00 pront search	4	Headlamp nozzle cover RH	1 pc	Serviceable	215.00	~	
Front bumper side retainer @ \$180/- 2 pcs Bent 1 pc - \$120 360.00 240 \left 360.00 Front bumper side retainer @ \$180/- 1 pc Bent 237.60 svc 237.60 \right 500 Front bumper reinforcement 1 pc Dented 948.00 svc 948.00 \right 510.00 svc 510.00 \right 510.00 svc 510.00 \right 520.00 Front bumper lower grille 1 pc Cracked 450.00 svc 450.00 \right 520.00 svc 450.00 \right 520.00 svc 450.00	5	Headlamp nozzle pump RH	1 pc	Serviceable	399.00	~	
Front bumper side retainer @ \$180/- 2 pcs Bent 1 pc - \$120 360.00 240 \( \sqrt{360.00} \) Front bumper bracket RH 1 pc Bent 237.60 svc 237.60 \( \sqrt{237.60} \) Front bumper reinforcement 1 pc Dented 948.00 svc 948.00 \( \sqrt{237.60} \) Front bumper sponge 1 pc Cracked 510.00 svc 510.00 \( \sqrt{250.00} \) Front bumper lower grille 1 pc Cracked 450.00 svc 450.00 \( \sqrt{250.00} \) Rear bumper reinforcement 1 pc Dented 697.00 566 \( \sqrt{697.00} \) Rear bumper inner lower garnish 1 pc Cracked 425.00 284 \( \sqrt{425.00} \) Rear bumper reverse sensor @ \$462/- 4-pcs- Malfunction 1pc - \$225464.00 450 \( \sqrt{464.00} \) Rear lamp RH 1 pc Cracked 1,848.00 528 \( \sqrt{1,848.00} \) Rear lamp side garnish RH 1 pc Cracked 320.50 SVC 320.50 \( \sqrt{250.00} \) Add special nett item Front bumper emblem 1 pc Necessary 101.80 101.80 \( \sqrt{250.00} \)	6	Front grille c/w chrome RH	1 pc	Cracked	420.00	420.00	<b>✓</b>
Front bumper bracket RH 1 pc Bent 237.60 svc 237.60 > Front bumper reinforcement 1 pc Dented 948.00 svc 948.00 > Front bumper sponge 1 pc Cracked 510.00 svc 510.00 > Front bumper lower grille 1 pc Cracked 450.00 svc 450.00 > Rear bumper inforcement 1 pc Dented 697.00 566 697.00    Rear bumper inner lower garnish 1 pc Cracked 425.00 284 425.00    Rear bumper reverse sensor @ \$462/- 4-pes- Malfunction 1pc - \$225464.00 450    Rear lamp RH 1 pc Cracked 1,848.00 528    Rear lamp side garnish RH 1 pc Cracked 320.50 svc 320.50     List price less 5% 709.43 678.73     Add special nett item    Front bumper emblem 1 pc Necessary 101.80 101.80     Front bumper reinforcement    1 pc Cracked 320.50 svc 320.50     Add special nett item    Front bumper emblem 1 pc Necessary 101.80 101.80     Front bumper garnish    1 pc Cracked 1,848.00 528     14,188.65 13,574.65     13,479.22 12,895.92	7	Front bumper	1 pc	Deformed	1,839.60	1244 🗸 1,839.60	
1 Front bumper reinforcement       1 pc       Dented       948.00 svc       948.00 svc       948.00 svc       948.00 svc       948.00 svc       948.00 svc       510.00 svc       510.00 svc       510.00 svc       510.00 svc       450.00 svc       425.00 svc       284 vc       425.00 svc       425.00 svc       425.00 svc       425.00 svc       464.00 s	8	Front bumper side retainer @ \$180/-	2 pcs	Bent 1 pc -	\$120 360.00	240 🗸 360.00	
1 Front bumper sponge 1 pc Cracked 510.00 svc 510.00 > 2 Front bumper lower grille 1 pc Cracked 450.00 svc 450.00 > 3 Rear bumper 1 pc Tom 1,907.35 1043 √1	9	Front bumper bracket RH	1 pc	Bent	237.60	SVC 237.60	X
2 Front bumper lower grille 1 pc Cracked 450.00 SVC 450.00 > 3 Rear bumper 1 pc Tom 1,907.35 1043 √1,907.35    4 Rear bumper reinforcement 1 pc Dented 697.00 566√ 697.00    5 Rear bumper inner lower garnish 1 pc Cracked 425.00 284 √ 425.00    6 Rear bumper reverse sensor @ \$462/- 4-pcs- Malfunction 1pc - \$225464.00 450 √ 464.00    7 Rear lamp RH 1 pc Cracked 1,848.00 528 √1,848.00    8 Rear lamp side garnish RH 1 pc Cracked 320.50 SVC 320.50     List price less 5% 709.43 678.73    13,479.22 12,895.92     Add special nett item    Front bumper emblem 1 pc Necessary 101.80 101.80 ✓	10	Front bumper reinforcement	1 pc	Dented	948.00	SVC 948.00	X
3 Rear bumper       1 pc       Tom       1,907.35 1043 √1,907.35         4 Rear bumper reinforcement       1 pc       Dented       697.00 566√ 697.00         5 Rear bumper inner lower garnish       1 pc       Cracked       425.00 284√ 425.00         6 Rear bumper reverse sensor @ \$462/-       4 pcs -       Malfunction 1pc - \$225464.00 450 √ 464.00         7 Rear lamp RH       1 pc       Cracked       1,848.00 528 √1,848.00         8 Rear lamp side garnish RH       1 pc       Cracked       320.50 SVC 320.50 ×         14,188.65       13,574.65       13,574.65         List price less 5%       709.43 678.73       678.73         13,479.22       12,895.92         Add special nett item       1 pc       Necessary       101.80       101.80 ✓	11	Front bumper sponge	1 pc	Cracked	510.00	SVC 510.00	X
4 Rear bumper reinforcement       1 pc       Dented       697.00       566√       697.00         5 Rear bumper inner lower garnish       1 pc       Cracked       425.00       284 ✓       425.00         6 Rear bumper reverse sensor @ \$462/-       4-pcs-       Malfunction 1pc - \$225464.00       450 ✓       464.00         7 Rear lamp RH       1 pc       Cracked       1,848.00       528 ✓ 1,848.00         8 Rear lamp side garnish RH       1 pc       Cracked       320.50       SVC       320.50       X         List price less 5%       709.43       678.73       13,479.22       12,895.92         Add special nett item       1 pc       Necessary       101.80       101.80	12	Front bumper lower grille	1 pc	Cracked	450.00	SVC 450.00	X
5 Rear bumper inner lower garnish       1 pc       Cracked       425.00       284 ✓ 425.00         6 Rear bumper reverse sensor @ \$462/-       4-pcs-       Malfunction 1pc - \$225464.00       450 ✓ 464.00         7 Rear lamp RH       1 pc       Cracked       1,848.00       528 ✓ 1,848.00         8 Rear lamp side garnish RH       1 pc       Cracked       320.50       SVC       320.50       SVC         List price less 5%       709.43       678.73         13,479.22       12,895.92         Add special nett item         9 Front bumper emblem       1 pc       Necessary       101.80       101.80	13	Rear bumper	1 pc	Tom	1,907.35	1043 🗸 1,907.35	
Rear bumper reverse sensor @ \$462/- 4-pes- Malfunction 1pc - \$225464.00 450 \( \sqrt{464.00} \) Rear lamp RH 1 pc Cracked 1,848.00 528 \( \sqrt{1,848.00} \) Rear lamp side garnish RH 1 pc Cracked 320.50 SVC 320.50 \( \sqrt{320.50} \) List price less 5% 709.43 678.73 13,479.22 12,895.92  Add special nett item Front bumper emblem 1 pc Necessary 101.80 101.80 \( \sqrt{101.80} \)	14	Rear bumper reinforcement	1 pc	Dented	697.00	566 ✓ 697.00	
7 Rear lamp RH       1 pc       Cracked       1,848.00       528 ✓ 1,848.00         8 Rear lamp side garnish RH       1 pc       Cracked       320.50       SVC       320.50       X         List price less 5%       709.43       678.73         13,479.22       12,895.92         Add special nett item       1 pc       Necessary       101.80       101.80	15	Rear bumper inner lower garnish	1 pc	Cracked	425.00	284 🗸 425.00	
Rear lamp side garnish RH 1 pc Cracked 320.50 SVC 320.50 > 14,188.65 13,574.65	16	Rear bumper reverse sensor @ \$462/-	4-pcs	Malfunction 1	pc - \$225464.00	450 🗸 464.00	
List price less 5%     14,188.65     13,574.65       709.43     678.73       13,479.22     12,895.92       Add special nett item     1 pc Necessary     101.80     101.80 ✓	17	Rear lamp RH	1 pc	Cracked	1,848.00	528 🗸 1,848.00	
List price less 5% 709.43 678.73  13,479.22 12,895.92  Add special nett item  Front bumper emblem 1 pc Necessary 101.80 101.80 ✓	18	Rear lamp side garnish RH	1 pc	Cracked	320.50	SVC 320.50	X
13,479.22 12,895.92  Add special nett item  9 Front bumper emblem 1 pc Necessary 101.80 101.80 ✓					14,188.65	13,574.65	38
Add special nett item  9 Front bumper emblem 1 pc Necessary 101.80 ✓		List price less 5%			709.43	678.73	
9 Front bumper emblem 1 pc Necessary 101.80 ✓					13,479.22	12,895.92	
		Add special nett item					
Pront number plate 1 pg Donted 50.00 50.00	19	Front bumper emblem	1 pc	Necessary	101.80	101.80	<b>✓</b>
or tront number place 1 pc Defiled 60.00 50.00 4	20	Front number plate	1 pc	Dented	60.00	50.00	40
1 Front bumper clip 10 pcs Necessary 80.00 70.00	21	Front bumper clip	10 pcs	Necessary	80.00	70.00	3
2 Rear bumper clips 10 pcs Necessary 80.00 70.00 3	22	Rear bumper clips	10 pcs	Necessary	80.00	70.00	30
3 Tail lamp clip 2 pcs Necessary40.00 30.00 ✓	23	Tail lamp clip	2 pcs	Necessary	40.00	30.00	<b>\</b>
361.80 321.80					361.80	321.80	

Our Ref: PA/SKH8154/0420/tpw

Vehicle No: SKH 8154 P

Our Ref: PA/SKH8154/0420/tpw

Labour charges			
To check wiring system (Front & Rear )	*	250.00	200.00 100
Remove & refit rear bumper sensor		200.00	180.00 30 \
Straighten end panel, rear fender & replace		1,500.00	1,200.00 700
damage parts Spray painting charges Conduct standard post repair		1,200.00	1,000.00 🗸
diagnostic scan		800.00	650.00 ×
		3,950.00	3,230.00
Total parts & labour concluded		<u>17,791.02</u>	<u>16,447.72</u>
Lump sum repair adjustment	6 repair days		<u>13,150.00</u>

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.


Prudent Adjustors Services Bok Jee Tan

## > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

/ehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: <b>Vehicle Details</b>	269J
Vehicle No.:	SKH8154P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Jun 2020
Vehicle Make:	B.M.W.
Vehicle Model:	316I 1.6 AT D/AB 4DR ABS HID
Primary Colour:	Red
Manufacturing Year:	2012
Engine No.:	B432J362N13B16A
Chassis No.:	WBA3A12050J719524
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,146.00
Original Registration Date:	18 Jan 2013
First Registration Date:	18 Jan 2013
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$23,146.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jan 2023
PARF Rebate Amount: Intended COE Rebate Details	\$13,887.00
COE Expiry Date:	17 Jan 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$92,100.00
COE Rebate Amount:	\$23,742.00

The information contained herein is correct as at 19 Jun 2020





Made in Germany 316i A75

BAYERISCHE MOTOREN WERKE AG
WBA3A12050J719524

3130 kg
1- 885 kg
2- 1125 kg


































































# Re-Survey





## Re-Survey





Re-Survey





Re-Survey





## Re-Survey





Re-Survey





Re-Survey





Re-Survey

