

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008196/R1RS3Q2
Date: 05/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100314675
Claimant Vehicle No :	GBG2127U	Insured Vehicle No :	SFM9576G
Date of Loss:	05/08/2020	Nature of Claim:	TP
		Claim No:	7409918449SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG2127U	Engine No:	199A90006320650
Make & Model:	FIAT FIORINO CARGO, 1.3 SX (A)	Chassis No:	ZFA22500006F35121
Reg. Date:	28/06/2017 (Man. Year: 2017)	Odometer:	30064 km
Colour:	Brown		
Engine Capacity:	1248 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,975.71	8,244.91	3,730.80	31.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,845.00	5,830.00	2,015.00	25.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,820.71	14,074.91	5,745.80	28.99
Approved Total (Overridden) (S\$)		11,200.00		

(S\$)	19,820.71	11,200.00	8,620.71	43.49
+ GST 7.00/7.00% (S\$)	1,387.45	784.00	603.45	43.49
Nett Amount (S\$)	21,208.16	11,984.00	9,224.16	43.49
+ Loss of Use (12.0 x S\$70.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		104.00		
Nett Liability (S\$)		12,930.00		
Global Sum Settlement (S\$)		12,900.00		

INSPECTION

Date of Assignment: 07/08/2020

Date Inspected: 07/08/2020

Estimated Period of Repair: 9.0 days

 Inspected At: 8 Tuas Ave 18
 Repairer: Goldbell Engineering Pte Ltd
Adjuster: MOHD RASUL**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LHS	Repair	2,036.55 F	*- F
2	1		*REAR DOOR - RHS	Bent	1,891.31 F	*1,891.31 F
3	1		*TYPE PLATE - FLORINO	Necessary	110.67 F	*110.67 F
4	1		*TYPE PLATE - SPORT	Necessary	110.35 F	*110.35 F
5	1		*TYPE PLATE - ECO JET	Necessary	88.14 F	*88.14 F
6	1		*ORNAMENT - FIAT BADGE	Necessary	145.77 F	*145.77 F
7	1		*MEDALLION - PROFESSIONAL	Necessary	124.55 F	*124.55 F
8	1		*PARKING SENSOR	Cracked	385.50 F	*385.50 F
9	1		*BUMPER, RR	Deformed	720.08 F	*720.08 F
10	1		*BUMPER REINFORCEMENT	Cracked	285.00 F	*285.00 F
11	1		*TOWING COVER	Missing	48.00 F	*48.00 F
12	1		*BUMPER BRACKET RHS	Necessary	38.50 F	*38.50 F
13	1		*SIDE PANEL - RH	Buckled	1,895.60 F	*1,895.60 F
14	1		*TYRE 185/65 R15	Punctured	245.00 F	*245.00 F
15	6		*CLIPS	Necessary	33.00 F	*33.00 F
16	1		*ELECTRIC LOCK DOOR, RH	Cracked	325.58 F	*325.58 F
17	1		*ELECTRIC LOCK RR DOOR, LH	Serviceable	283.20 F	*- F
18	1		*REAR TAILLAMP RH	Cracked	485.00 F	*485.00 F
19	1		*GUIDE CENTER DS	Serviceable	248.95 F	*- F
20	1		*GUIDE LOWER DS	Serviceable	348.88 F	*- F
21	1		*RH SLIDING DOOR SENSOR	Serviceable	298.22 F	*- F
22	1		*DOOR HINGE, RR LOWER	Bent	68.95 F	*68.95 F
23	1		*SPLASH GUARD RR RH	Torn	195.55 F	*195.55 F
24	1		*TRIMMING GUM	Necessary	258.86 F	*258.86 F
25	1		*REAR END PANEL (PILLAR)	Serviceable	455.00 F	*- F
26	1		*REAR DOOR SEALING GASKET	Necessary	295.50 F	*295.50 F
27	1		*ENTRANCE COVER	Deformed	254.00 F	*254.00 F
28	1		*70 KM/H STICKER	Necessary	20.00 FS	*15.00 FS
29	1		*4 PAC STICKER	Necessary	20.00 FS	*15.00 FS
30	2		*WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
31	2		*PANEL GUM	Necessary	80.00 FS	*80.00 FS
32	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)
11,975.71
8,244.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN.	New	4,200.00	3,300.00
2	TO PUTTY, CLEAN, SPRAY PAINT AND PLOLISH, ETC.	New	2,100.00	1,400.00
3	TO REMOVE AND REFIX REAR DOOR GLASS TO ASSIST REPAIR, LH.	New	180.00	120.00
4	TO REMOVE AND REFIX REAR DOOR GLASS TO ASSIST REPAIR, RH.	New	180.00	120.00
5	TO REALIGN RH SLIDING DOOR.	New	450.00	300.00
6	TO APPLY TUFF COAT.	New	75.00	50.00
7	TO REMOVE AND REFIT TYRE AND WHEEL BALANCING.	New	80.00	60.00
8	TO REMOVE AND REFIX INNER TRIM TO ASSIST REPAIR.	New	400.00	300.00
9	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK.	New	180.00	180.00
Gross Labour Cost (\$\$)			7,845.00	5,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >