

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20008200/AVF3E2
Date: 05/01/2021

REFERENCE

Insured/Claimant:	VISHAL AGARWAL	Policy No:	1900093767		
Date of Loss:	06/08/2020	Nature of Claim:	OD	Claim No:	5937117334SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK9638P		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX052277
Reg. Date:	30/04/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF5K2044398
Colour:	White	Odometer:	18160 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$170,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R19	Rear Tyre Size:	235/55R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,033.00	2,787.60	3,245.40	53.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,112.00	2,112.00	6,000.00	73.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,145.00	4,899.60	9,245.40	65.36
+ GST 7.00/7.00% (S\$)	990.15	342.97	647.18	65.36
Nett Amount (S\$)	15,135.15	5,242.57	9,892.58	65.36

INSPECTION

Date of Assignment:	07/08/2020		
Date Inspected:	07/08/2020	Inspected At:	24 BENOI SECTOR Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	474.00 FS	*- FS
2	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	171.00 FS	*- FS
3	2		*FRONT WHEEL COVER-LH/RH	Not Necessary	1,250.00 FS	*- FS
4	2		*ALUMINIUM RIM-LH FRONT/REAR	Cut	2,182.00 FS	*1,745.60 FS
5	2		*TYRE - FRONT LH / REAR LH	Punctured	720.00 FS	*720.00 FS
6	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
7	1		*UNDERBODY TRIM LHS	Torn	403.00 FS	*322.00 FS
8	1		*LOWER ARM FRONT LHS	Not Necessary	533.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	6,033.00	2,787.60
--------------------------	-----------------	-----------------

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW BACK FROM ACCIDENT SCENE	New	280.00	0.00
2	TO REMOVE AND TRANSFER/REINSTALL FRONT BUMPER WIRE HARNESS FOR FRONT PARKING AID SYSTEM	New	280.00	0.00
3	TO DISMANTLE FRONT BUMPER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS	New	1,200.00	0.00
4	TO RESPRAY FRONT BUMPER AND BOTH FRONT WHEEL ARCH TRIMS	New	2,000.00	550.00
5	TO RENEW LHS FRONT RIM WITH TYRE AND LHS REAR RIM WITH TYRE.TO CARRY OUT PRE-WHEEL ALIGNMENT AND POST WHEEL ALIGNMENT.TO INSPECT LHS FRONT WHEEL SUSPENSION AND LHS REAR WHEEL SUSPENSION FOR FURTHER DAMAGES	New	560.00	320.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO REPAIR LHS JACKING POINT.	New	800.00	500.00
8	TO RESPRAY LHS JACKING POINT.	New	1,000.00	550.00
9	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY.	New	1,800.00	-
Gross Labour Cost (\$\$)			8,112.00	2,112.00

LKK Auto Consultants Pte Ltd/SMK9638P/05/01/2021 15:50

< END OF ESTIMATES >