

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20008213/KDA3Q2

**Date:** 26/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100507583

**Claimant**  
**Vehicle No :** SKF5768Z **Insured Vehicle No :** SJC1166P

Date of Loss: 05/08/2020 Nature of Claim: TP Claim No: 9399719034SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKF5768Z</b>		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	1ZRX179740
Reg. Date:	15/06/2012 (Man. Year: 2012)	Chassis No:	MR053REE104132669
Colour:	Metallic Silver	Odometer:	113495 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,320.60	907.87	3,412.73	78.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	880.00	2,200.00	71.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,400.60</b>	<b>1,787.87</b>	<b>5,612.73</b>	<b>75.84</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,400.00</b>		
<b>(\$\$)</b>	7,400.60	1,400.00	6,000.60	81.08
<b>+ GST 7.00/7.00% (\$\$)</b>	518.04	98.00	420.04	81.08
<b>Nett Amount (\$\$)</b>	<b>7,918.64</b>	<b>1,498.00</b>	<b>6,420.64</b>	<b>81.08</b>
<b>+ Car Rental (3.0 x S\$120.00/day) (\$\$)</b>		360.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>1,860.00</b>		

### INSPECTION

Date of Assignment: 06/08/2020

Date Inspected: 07/08/2020 Inspected At:

BH Auto Services Pte Ltd (Sin Ming)  
Blk 1 Sin Ming Industrial Estate Sector  
C, #01/111/113/115/117  
Singapore 575636

Estimated Period of Repair: 3.0 days

---

**Adjuster:** KENNETH KONG**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	437.00 FL	*437.00 FL
2	1		*FRONT BUMPER CLIP	Necessary	5.50 FL	*5.50 FL
3	1		*FRONT BUMPER RETAINER L	Serviceable	55.00 FL	*- FL
4	1		*FRONT BUMPER RETAINER R	Distorted	55.00 FL	*55.00 FL
5	1		*FRONT BONNET	Repair	901.00 FL	*- FL
6	1		*FRONT FENDER	Repair	610.00 FL	*- FL
7	1		*FRONT FENDER GUARD	Serviceable	165.00 FL	*- FL
8	1		*FRONT FENDER GUARD CLIP	Not Necessary	5.50 FL	*- FL
9	1		*FRONT HEADLIGHT R	Cut	713.00 FL	*713.00 FL
10	1		*FRONT SUPPORT PANEL	Repair	721.00 FL	*- FL
11	1		*FRONT BUMPER FOG LAMP COVER R	Serviceable	85.00 FL	*- FL
12	1		*HEAD LAMP ASSY R	Repeated	450.00 FL	*- FL
13	1		*HEAD LAMP LOWER BRACKET R (NPA)	Not Necessary	0.00 FL	*- FL
14	1		*FRONT BUMPER REINFORCEMENT	Repair	345.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,548.00</b>	<b>1,210.50</b>
<b>- List Item Discount on L Items 5.00/25.00% (\$\$)</b>	227.40	302.63
<b>Total Parts (\$\$)</b>	<b>4,320.60</b>	<b>907.87</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT ,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS (FRONT)	New	1,500.00	400.00
2	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATE (FRONT)	New	1,200.00	400.00
3	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	80.00	20.00
4	PROVIDE SKILL LABOUR TO WHEEL ALIGNMENT	New	150.00	60.00
5	PROVIDE SKILL LABOUR FOR UNDERCARRIAGE (FRONT)	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,080.00</b>	<b>880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >