

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20008214/ARA3Q2

Date: 23/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900244278
Claimant Vehicle No :	SMR8098S	Insured Vehicle No :	YP103G
Date of Loss:	05/08/2020	Nature of Claim:	TP
		Claim No:	9590701458SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR8098S		
Make & Model:	BMW 216I, 1.5 (A)	Engine No:	40285882B38A15A
Reg. Date:	22/01/2020 (Man. Year: 2019)	Chassis No:	WBA6V120105P77446
Colour:	Black	Odometer:	35893 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,331.92	3,410.55	1,921.37	36.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	1,280.00	930.00	42.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,541.92	4,690.55	2,851.37	37.81
+ GST 7.00/7.00% (\$\$)	527.93	328.34	199.59	37.81
Nett Amount (\$\$)	8,069.85	5,018.89	3,050.96	37.81
+ Loss of Use (4.0 x \$S\$60.00/day) (\$\$)		240.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		5,260.89		

INSPECTION

Date of Assignment:	07/08/2020		
Date Inspected:	07/08/2020	Inspected At:	1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Singapore 415933
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	1,321.90 FL	*1,321.90 FL
2	10		*BONNET INSULATOR CLIP	Not Necessary	68.00 FL	*- FL
3	1		*LHF FENDER	Dented	725.30 FL	*725.30 FL
4	1		*LHF FENDER LINER CLIP	Not Necessary	34.00 FL	*- FL
5	1		*LHF FENDER QUARTER GLASS WITH MOULDING	Not Necessary	289.36 FL	*- FL
6	1		*LHF HEADLAMP	Cut	1,580.60 FL	*1,580.60 FL
7	1		*FRONT BUMPER	Repair	1,298.30 FL	*- FL
8	10		*FRONT BUMPER CLIP	Not Necessary	68.00 FL	*- FL
9	1		*BMW FRONT BUMPER LOGO	Not Necessary	120.70 FL	*- FL
10	1		*LHF FENDER INNER MOULDING	Cracked	71.90 FL	*71.90 FL
11	1		*LHF FENDER INNER BRACKET	Bent	89.80 FL	*89.80 FL
12	1		*LHF BUMPER BRACKET	Not Necessary	58.10 FL	*- FL
13	1		*LHF HEADLAMP LOWER BRACKET	Not Necessary	198.40 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,924.36	3,789.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	592.44	378.95
Total Parts (\$\$)	5,331.92	3,410.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	800.00	500.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	1,000.00	750.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	30.00	30.00
4	S.R.S RESET OF SYSTEM	New	300.00	0.00
5	TO REFOCUS HEADLAMP	New	80.00	0.00
Gross Labour Cost (S\$)			2,210.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >