

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20008216/AES3Q2

Date: 01/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993949

Claimant
Vehicle No : SLV6664L **Insured Vehicle No :** GBK4490K

Date of Loss: 07/08/2020 Nature of Claim: TP Claim No: 1433708874SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV6664L		
Make & Model:	HONDA SHUTTLE, 1.5 G (A)	Engine No:	L15B5460148
Reg. Date:	09/01/2018 (Man. Year: 2017)	Chassis No:	GK81200117
Colour:	Blue	Odometer:	21348 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,027.72	8,222.20	3,805.52	31.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,670.00	2,770.00	1,900.00	40.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,697.72	10,992.20	5,705.52	34.17
Approved Total (Overridden) (S\$)		8,800.00		
Nett Amount (S\$)	16,697.72	8,800.00	7,897.72	47.30
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
Nett Liability (S\$)		9,340.00		

INSPECTION

Date of Assignment: 07/08/2020

Date Inspected: 07/08/2020 Inspected At:

Advance Auto Garage (HQ)
23 KAKI BUKIT AVENUE 4 #04-01
AAS KAKI BUKIT CENTRE
Singapore 415933

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP	Not Necessary	51.60 FL	*- FL
2	1		*REAR BUMPER	Distorted	956.00 FL	*956.00 FL
3	2		*REAR BUMPER SIDE HOLDER	Necessary	53.00 FL	*53.00 FL
4	1		*REAR BUMPER SIDE COVER RH	Deformed	55.00 FL	*55.00 FL
5	1		*REAR BUMPER SIDE COVER REFLECTOR RH	Cut	45.00 FL	*45.00 FL
6	1		*REAR BUMPER SPONGE RH	Not Necessary	89.50 FL	*- FL
7	1		*REAR BUMPER UNDERCOVER RH	Not Necessary	95.20 FL	*- FL
8	1		*REAR BUMPER TOW COVER	Not Necessary	25.20 FL	*- FL
9	1		*REAR END PANEL	Dented	560.80 FL	*560.80 FL
10	1		*REAR END PANEL TOP GARNISH	Deformed	155.50 FL	*155.50 FL
11	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	105.00 FL	*- FL
12	1		*REAR END PANEL BUZZER SENSOR	Not Necessary	85.00 FL	*- FL
13	2		*TAILLAMP	N/S Cut / O/S Cracked	1,041.00 FL	*1,041.00 FL
14	1		*TAILLAMP PANEL RH	Repair	268.00 FL	*- FL
15	1		*TAILLAMP INNER PANEL RH	Repair	210.20 FL	*- FL
16	1		*TAILGATE	Distorted	1,193.00 FL	*1,193.00 FL
17	1		*TAILGATE LOCK	Damaged	187.50 FL	*187.50 FL
18	1		*TAILGATE WEATHERSTRIP	Cut	168.50 FL	*168.50 FL
19	1		*TAILGATE OUTER LOCK SWITCH	Not Necessary	175.50 FL	*- FL
20	2		*TAILGATE REFLECTOR	N/S Cut / O/S Cracked	790.00 FL	*790.00 FL
21	1		*TAILGATE INNER PULL POCKET	Deformed	25.00 FL	*25.00 FL
22	1		*TAILGATE INNER TRIM BOARD	Cut	320.00 FL	*320.00 FL
23	1		*TAILGATE GLASS	Shattered	1,210.10 FL	*1,210.10 FL
24	1		*TAILGATE GLASS MOULDING	Necessary	120.00 FL	*120.00 FL
25	1		*TAILGATE WIPER MOTOR	Not Necessary	375.20 FL	*- FL
26	1		*TAILGATE OUTER GARNISH	Cracked	383.10 FL	*383.10 FL
27	1		*TAILGATE WIPER BLADE	Cut	66.50 FL	*66.50 FL
28	2		*TAILGATE DAMPER	Not Necessary	330.00 FL	*- FL
29	2		*TAILGATE HINGE	Not Necessary	101.00 FL	*- FL
30	1		*HONDA LOGO	Necessary	38.00 FL	*38.00 FL
31	1		*SHUTTLE EMBLEM	Necessary	55.00 FL	*55.00 FL
32	1		*REAR FENDER INNER TRIM BOARD RH	Cracked	489.60 FL	*489.60 FL
33	1		*REAR FENDER INNER TRIM BOARD UPPER RH	Deformed	298.40 FL	*298.40 FL
34	1		*FLOOR PANEL	Repair	1,180.00 FL	*- FL
35	1		*FLOOR PANEL TOP COVER	Deformed	585.50 FL	*585.50 FL
36	1		*REAR EXHAUST PIPE	Not Necessary	745.00 FL	*- FL
37	1		*REAR EXHAUST MOUNTING	Not Necessary	33.00 FL	*- FL
38	1		*REAR NUMBER PLATE	Deformed	30.00 FS	*30.00 FS
39	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
40	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
41	1		*SET REAR BUMPER UNDERCOVER CLIPS	Not Necessary	20.00 FS	*- FS
42	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
43	1		*SET REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
44	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
45	1		*SET TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
46	2		*TAILGATE GLASS SIDE GARNISH (BLACK)	Cut	240.00 FS	*240.00 FS
47	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
48	1		*SET SET REAR FENDER INNER TRIM BOARD UPPER CLIPS	Necessary	25.00 FS	*25.00 FS
49	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*REAR VIDEO RECORDER	Damaged	580.00 FS	*450.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	14,560.90
					9,981.50	
					- List Item Discount on L Items 20.00/20.00% (\$\$)	2,533.18
						1,759.30
					Total Parts (\$\$)	12,027.72
						8,222.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	1,600.00	1,000.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,500.00	1,000.00
3	WIRING CHECK	New	100.00	30.00
4	TUFF COAT	New	150.00	80.00
5	TO REMOVE AND REFIT REVERSE SENSORS	New	100.00	60.00
6	TO REMOVE AND REFIT REAR CAMERA	New	100.00	60.00
7	TO REMOVE AND REFIT REAR VIDEO CAMERA	New	100.00	60.00
8	TO REMOVE AND REFIT REAR WINDSCREEN	New	180.00	120.00
9	TO REMOVE AND REFIT UPHOLSTERY	New	150.00	100.00
10	TO REMOVE AND REFIR FUEL TANK	New	150.00	0.00
11	TO TRANSFER TAILGATE FITTINGS AND TOP SPOILER	New	180.00	120.00
12	TO REMOVE AND REFIT EXHAUST PIPE	New	150.00	0.00
13	TOWING FEES	New	60.00	60.00
14	TO REMOVE AND CLEAN INTERIOR OF GLASS SHIELD	New	150.00	80.00
Gross Labour Cost (\$\$)			4,670.00	2,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >