

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Low

Date: 19 Aug 2020

Preliminary Advice

Insured Vehicle No	: SJN1791B	Accident Date	: 31/01/2020
TP Vehicle No	: SKM7172S	Assignment Date	: 07/08/2020
Make	: LEXUS GS250	Est. Duration of Repair	: 2
Date of Inspection	: 19/08/2020		
Inspection At	: K KIM HIN AUTO PTE LTD BLK 34 SIN MING DRIVE,#01-114, SINGAPORE 575708		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	700.00
Revised Amount	:S\$	520.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	520.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :