

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20008234/KGS3Q2

Date: 16/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLV1533P	Insured Vehicle No :	SHA7824T
Date of Loss: 01/08/2020	Nature of Claim: TP	Claim No: MCT20080008

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV1533P		
Make & Model:	TOYOTA C-HR HYBRID, 1.8 E G CVT (A)	Engine No:	2ZR8194711
Reg. Date:	22/12/2017 (Man. Year: 2017)	Chassis No:	ZYX102075097
Colour:	Metallic Pearl White	Odometer:	75916 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,064.55	982.20	82.35	7.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	805.00	575.00	41.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,444.55	1,787.20	657.35	26.89
+ GST 7.00/7.00% (\$\$)	171.12	125.10	46.02	26.89
Nett Amount (\$\$)	2,615.67	1,912.30	703.37	26.89
+ Loss of Use (3.0 x S\$80.00/day) (\$\$)		240.00		
		2,152.30		
		2,150.00		

INSPECTION

Date of Assignment:	11/08/2020		
Date Inspected:	12/08/2020	Inspected At:	Optima Werkz Pte Ltd (HQ)
			6 Kung Chong Road
			Singapore 159143
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Sep 2020)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 E G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV1533P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	878.60 FL	*878.60 FL
2	8		*REAR BUMPER CLIPS	Necessary	44.00 FL	*44.00 FL
3	1		*REAR BUMPER LOWER LIP COVER	Cracked	496.80 FL	*387.00 FL
4	1		*REAR TAILGATE (NPA)	Repair	0.00 FL	*- FL
5	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
					Sub Total (\$\$)	1,419.40
					- List Item Discount on L Items 25.00/25.00% (\$\$)	354.85
					Total Parts (\$\$)	1,064.55
						982.20

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	500.00	300.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER ,REAR TAILGATE ,REAR END PANEL & ETC	New	700.00	440.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC TO EFFECT REPLACE OF REAR BUMPER	New	100.00	50.00
4	TO CHECK WIRING & ELECTRICAL WIRING SYSTEM	New	80.00	15.00
Gross Labour Cost (\$\$)			1,380.00	805.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >